
Homework



A steel plate (width W=2cm, length L=10cm, thickness D=1cm, conductivity=43.3W/m $^{\circ}$ C) is used to conduct the heat from the hot end (T_1 =100 $^{\circ}$ C) to cold end (T_2 =20 $^{\circ}$ C).

- (a) How many watts of the heat (Q) can be conducted through the steel plate?
- (b) How to improve the heat transfer capability based on the same hot end (T₁=100°C) and cold end (T₂=20°C) temperatures?



Heat Transfer Mechanism-Conduction



- Conduction in a solid is the transfer of heat from one point in the solid to another as a result of a temperature gradient.
- Conduction cannot occur in a vacuum. Molecules must be present for conduction to take place.

Conduction equation : Q = -KA dT/dx; or $Q = KA (T_1-T_2)/X$

Where, Q= rate of heat conduction along the X direction, W


K= thermal conductivity, W/m°C

A= cross-section area of the path, m²

dT/dX= temperature gradient along the path, °C /m

T₁, T₂= surface temperature, °C

X= distance between T₁ & T₂



TASA 國家太空中心
 Taiwan Space Agence

This document contains proprietary and controlled information of Taiwan Space Agency (TASA) and shall not be duplicated in whole or in part for any purposes without permission from TASA.

In [3]: import numpy as np

A = D * W

```
# Given values
k = 43.3  # Thermal conductivity in W/m°C
W = 0.02  # Width in meters
L = 0.1  # Length in meters
D = 0.01  # Thickness in meters
T1 = 100  # Hot end temperature in °C
T2 = 20  # Cold end temperature in °C
# Cross-sectional area
```

```
# Temperature difference
delta_T = T1 - T2

# Heat conducted using Fourier's law
Q = (k * A * delta_T) / L

# Output results
Q
```

Out[3]: 6.927999999999999

(b) How to improve heat transfer capability:

There are several ways to improve the heat transfer capability while maintaining the same temperature difference:

- 1. Increase thermal conductivity ((k)):
 - Use a material with higher thermal conductivity.
- 2. Increase the cross-sectional area ((A)):
 - Increase either the width ((W)) or length ((L)) of the steel plate.
- 3. Reduce thickness ((D)):
 - Make the plate thinner.
- 4. Use a better thermal interface material:
 - Place a high-conductivity material between the steel plate and the heat sources.