Stepper Motor Interfacing with Firebird V LPC2148 ARM7

Joel M. Pinto and Vishal Rajai eYantra Summer Internship – 2014 Embedded Real-Time Systems Lab Indian Institute of Technology, Bombay

> IIT Bombay July 7, 2014



Agenda for Discussion

- Introduction
 - What is a stepper motor?
 - Types of Stepper Motors
- 2 Controlling a Stepper Motor
 - Stepping sequences
 - Wave Stepping
 - Full Stepping
 - Half Stepping
 - Comparison of stepping modes
- 3 Identifying the wires of a stepper motor
- Stepper Motor Driver
- 5 Interfacing with LPC2148
 - GPIO pins
 - Code





What is a stepper motor?





What is a stepper motor?



Rotates in discrete steps



What is a stepper motor?



- Rotates in discrete steps
- Can hold or move to a position








Bipolar


Has 4 wires








- Bipolar
 - Has 4 wires




- Unipolar
 - Has 5 or 6 wires









We will use a unipolar stepper motor.



Introduction
Controlling a Stepper Motor
Identifying the wires of a stepper motor
Stepper Motor Driver
Interfacing with LPC2148

Stepping sequences Wave Stepping Full Stepping Half Stepping Comparison of stepping modes

Stepping sequences



Introduction
Controlling a Stepper Motor
Identifying the wires of a stepper motor
Stepper Motor Driver
Interfacing with LPC2148

Stepping sequences Wave Stepping Full Stepping Half Stepping Comparison of stepping modes

Stepping sequences

Wave Stepping



Stepping sequences Wave Stepping Full Stepping Half Stepping Comparison of stepping modes

Stepping sequences

- Wave Stepping
- Full Stepping





Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping modes

Stepping sequences

- Wave Stepping
- Full Stepping
- 6 Half Stepping



Introduction
Controlling a Stepper Motor
Identifying the wires of a stepper motor
Stepper Motor Driver
Interfacing with LPC2148

Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping modes

Wave Stepping



Wave Stepping


Step	Coil A	A Coil B Coil C		Coil D	
1	1	0	0	0	
2	0	1	0	0	
3	0	0	1	0	
4	0	0	0	1	

Table: Wave stepping sequence



Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping mode

Wave Stepping (contd.)



Stepper Motor's positions in the wave stepping sequence





Introduction
Controlling a Stepper Motor
Identifying the wires of a stepper motor
Stepper Motor Driver
Interfacing with LPC2148

Stepping sequences Wave Stepping Full Stepping Half Stepping Comparison of stepping modes

Full Stepping



Full Stepping

Step	Coil A	Coil B	Coil C	Coil D	
1	1	1	0	0	
2	0	1	1	0	
3	0	0	1	1	
4	1	0	0	1	

Table: Full stepping sequence



Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping modes

Full Stepping (contd.)



Stepper Motor's positions in the full stepping sequence



Introduction
Controlling a Stepper Motor
Identifying the wires of a stepper motor
Stepper Motor Driver
Interfacing with LPC2148

Stepping sequences Wave Stepping Full Stepping Half Stepping

Half Stepping



Half Stepping


Step	Coil A	Coil B	Coil C	Coil D
1	1	0	0	0
2	1	1	0	0
3	0	1	0	0
4	0	1	1	0
5	0	0	1	0
6	0	0	1	1
7	0	0	0	1
8	1	0	0	1

Table: Half stepping sequence



Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping mode

Half Stepping (contd.)



Stepper Motor's positions in the half stepping sequence



Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping modes

Comparison of stepping modes



Stepping sequences
Wave Stepping
Full Stepping
Half Stepping
Comparison of stepping modes

Comparison of stepping modes

Stepping Mode

- Torque
- Wibration
- Speed
- Resolution

Wave Stepping

- Lowest
- ② Intermediate
- Full
- Normal

Full Stepping

- Highest
- 4 Highest
- 3 Full
- O Normal

Half Stepping

- Intermediate
- Lowest
- B Halved
- Oubled






Identifying the wires of a stepper motor





Stepper Motor Driver Circuit





Interfacing with LPC2148 GPIO pins



Interfacing with LPC2148 GPIO pins

JTAG connector pin	MCU pin	Connected to
11	P1.26	ULN2003 pin 1
13	P1.27	ULN2003 pin 2
5	P1.28	ULN2003 pin 3
9	P1.29	ULN2003 pin 4
4	GND	ULN2003 pin 8

Table: GPIO pins used



Interfacing with LPC2148 GPIO pins

JTAG connector pin	MCU pin	Connected to
11	P1.26	ULN2003 pin 1
13	P1.27	ULN2003 pin 2
5	P1.28	ULN2003 pin 3
9	P1.29	ULN2003 pin 4
4	GND	ULN2003 pin 8

Table: GPIO pins used

19	17	15	13	11	9	7	5	3	1
20	18	16	14	12	10	8	6	4	2

Figure: Pin numbering on the JTAG connector



Interfacing with LPC2148 Code





Interfacing with LPC2148

```
#include
```

```
#include <lpc214x.h>
#include "stepper.h"
```





Interfacing with LPC2148

```
#include
#include <1pc214x.h>
#include "stepper.h"
```

```
int direction = 1;
int count = 0;
int main(void)
{
    stepper_port_init();//Initialize ports
```





Interfacing with LPC2148 Code

```
#include
#include <1pc214x.h>
#include "stepper.h"
```

```
int direction = 1;
int count = 0;
int main(void)
    stepper_port_init();//Initialize ports
    while(1)
        full_step(direction);
```






Interfacing with LPC2148 Code

```
#include
#include <1pc214x.h>
#include "stepper.h"
```

```
int direction = 1;
int count = 0;
int main(void)
    stepper_port_init();//Initialize ports
    while(1)
        full_step(direction);
        DelaymSec(10): //10 ms between steps equals 100Hz
```





Interfacing with LPC2148 Code

```
#include
#include <1pc214x.h>
#include "stepper.h"
```

```
int direction = 1;
int count = 0;
int main(void)
    stepper_port_init();//Initialize ports
    while(1)
        full_step(direction);
        DelaymSec(10); //10 ms between steps equals 100Hz
        if(count++ >= 200) //Change direction every revolution
            direction = -1 * direction;
            count = 0:
```





Interfacing with LPC2148 Code (contd.)

Port Initialisation







Thank You!

Send your queries to: helpdesk@e-yantra.org



