Interfacing Servo Motor with ARM (Firebird V)

Joel M. Pinto and Vishal H. Rajai eYantra Summer Internship'14 Embedded Real-Time Systems Lab Indian Institute of Technology, Bombay

> IIT Bombay July 21, 2014



Agenda of Discussion

- Introduction
- Servo motor
 - Principle and Working
 - Operating Servo Motor
 - Selection of Servo motor
- **3** ARM7 LPC2148
 - Generating PWM signals
 - Code





Prerequisite knowledge

- Basic IO Interfacing using ports
- Working with PWM registers of ARM7 LPC2148.





Introduction

- Servo motors (or servos) are self-contained devices that rotate or push parts of a machine with great precision.
- Servos can put out about 42 oz/in of torque.
- Relatively inexpensive.
- Widely used for educational purpose in mechatronics as they can be controlled by a microcontroller.





A servo mainly contains:





- A servo mainly contains:
 - dc motor





- A servo mainly contains:
 - dc motor
 - gear train





- A servo mainly contains:
 - dc motor
 - gear train
 - potentiometer





- A servo mainly contains:
 - dc motor
 - gear train
 - potentiometer
 - control circuitry.






- A servo mainly contains:
 - dc motor
 - gear train
 - potentiometer
 - control circuitry.
- Forming closed loop control system.











 As shown in figure, control signal and output signal are fed to error detector.





- As shown in figure, control signal and output signal are fed to error detector.
- Resultant signal from error detector acts as input to the dc motor to rotate.





- As shown in figure, control signal and output signal are fed to error detector.
- Resultant signal from error detector acts as input to the dc motor to rotate.
- Also rotating the potentiometer knob coupled with its shaft via gears.





- As shown in figure, control signal and output signal are fed to error detector.
- Resultant signal from error detector acts as input to the dc motor to rotate.
- Also rotating the potentiometer knob coupled with its shaft via gears.
- Reaching desired angle, there would not be any difference in the signals fed to error detector.






- As shown in figure, control signal and output signal are fed to error detector.
- Resultant signal from error detector acts as input to the dc motor to rotate.
- Also rotating the potentiometer knob coupled with its shaft via gears.
- Reaching desired angle, there would not be any difference in the signals fed to error detector.
- Resulting in motor to stop rotating and wait at that position





Operating servo motor

 'on-time' of a PWM signal is used as control signal to rotate motor at particular angle.







 This time period depends on the servo used and not on total time period or duty cycle of PWM signal.





- This time period depends on the servo used and not on total time period or duty cycle of PWM signal.
- Values of on-time for rotating servo to 0 and 180 degree are provided by the manufacturer in data sheet.





- This time period depends on the servo used and not on total time period or duty cycle of PWM signal.
- Values of on-time for rotating servo to 0 and 180 degree are provided by the manufacturer in data sheet.
- Graph of on-time period vs. angle is linear.





- This time period depends on the servo used and not on total time period or duty cycle of PWM signal.
- Values of on-time for rotating servo to 0 and 180 degree are provided by the manufacturer in data sheet.
- Graph of on-time period vs. angle is linear.
- Range of PWM frequency for operating servo is 40-60 Hz









Servo is selected based on its:

Torque





- Torque
- Speed





- Torque
- Speed
- Weight






- Torque
- Speed
- Weight
- Dimensions





Servo connector



- 1- Ground
- 2- Power
- 3- Control signal
- 4- Connector to controller






Interfacing servo with Firebird V





Servo Connectors location





Servo Connectors Schematic

Single edged PWM is used here to rotate servo motor.

• Let the Prescaler, PWMPR=120





- Let the Prescaler, PWMPR=120
- $f_{cpu} = 12000000 Hz$





- Let the Prescaler, PWMPR=120
- $f_{cpu} = 12000000Hz$
- ullet Let the frequency of the PWM signal be $=50~\mathrm{Hz}$





- Let the Prescaler, PWMPR=120
- $f_{cpu} = 12000000Hz$
- Let the frequency of the PWM signal be = 50 Hz That gives, PWMMR0 = 2000





- Let the Prescaler, PWMPR=120
- $f_{cpu} = 12000000Hz$
- Let the frequency of the PWM signal be = 50 Hz That gives, PWMMR0 = 2000
- Values of registers like PWMTCR and PINSEL can be found using ARM7 LPC2148 datasheet.





• Calculating value of PWMMR1: Prescaler = 120





• Calculating value of PWMMR1:

Prescaler = 120

That increments counter every 120/12000000 = 0.01 ms





- Calculating value of PWMMR1:
 Prescaler = 120
 That increments counter every 120/12000000 = 0.01 ms
- Counts to be set to get 0.6 ms on-time period to rotate servo to 0° will be = 0.6/0.01 = 60





- Calculating value of PWMMR1:
 Prescaler = 120
 That increments counter every 120/12000000 = 0.01 ms
- Counts to be set to get 0.6 ms on-time period to rotate servo to 0° will be = 0.6/0.01 = 60 Similarly, for 180° , count value = 220





- Calculating value of PWMMR1:
 Prescaler = 120
 That increments counter every 120/12000000 = 0.01 ms
- Counts to be set to get 0.6 ms on-time period to rotate servo to 0° will be = 0.6/0.01 = 60 Similarly, for 180° , count value = 220
- As the relation between on-time period and corresponding degree is linear, so is the relation between the count value in PWMMR1 and degree





- Calculating value of PWMMR1:
 Prescaler = 120
 - That increments counter every 120/12000000 = 0.01 ms
- Counts to be set to get 0.6 ms on-time period to rotate servo to 0° will be = 0.6/0.01 = 60 Similarly, for 180° , count value = 220
- As the relation between on-time period and corresponding degree is linear, so is the relation between the count value in PWMMR1 and degree

```
That gives, PWMMR1 = (degrees/1.125) + 60.0
```









Header files





Header files

#include <1pc214x.h>





Header files

#include <1pc214x.h>

Main Logic





Header files

#include <1pc214x.h>

Main Logic

```
float PositionPanServo = 0;
PositionPanServo = ((float)degrees / 1.125) + 60.0;
UpdateServoPos((unsigned int)PositionPanServo);
```





Thank You!

Post your queries on: helpdesk@e-yantra.org



