

Assignment – Lecture 64

1. A 25 kVA, 2000/200 V transformer has constant loss, i.e., iron loss of 350 W and full load copper loss of 400 W. Calculate the efficiency of the transformer at

- i) Full Load and 0.8 pf lagging
- ii) Half Load and 0.8 pf lagging

PES University