

Assignment – Lecture 63

1. Write a short note on

- i) core losses
- ii) copper losses

w.r.t a single-phase transformer.

PES University