Punjab Civil Defence & Fire Safety Services

Fire Safety Inspection Report & Certificate

Report Ref: FSC-2025-04471 | Inspection Type: Annual Renewal Inspection

SAMPLE / SYNTHETIC DOCUMENT — generated for AuditReady AI testing purposes only.

1. Facility Information

Facility Name	Al-Rehman Textiles (Pvt.) Ltd.
Facility Address	Plot 14, Industrial Estate, Faisalabad, Punjab
Facility Type	Garment manufacturing — sewing, cutting, finishing, packing
Floor Area Inspected	Approx. 42,000 sq. ft. (Ground + First Floor)
Occupancy at Time of Inspection	Approx. 310 workers across two shifts
Inspection Date	12 May 2025
Certificate Valid Until	12 May 2026 (standard 12-month validity)
Inspecting Officer	Fire Safety Inspector, Reg. No. FSI-0392
Overall Result	PASSED — subject to annual renewal

2. Purpose of Inspection

This inspection was carried out to assess the facility's compliance with the Punjab Fire Safety Code requirements applicable to industrial premises, and to renew the facility's annual Fire Safety Certificate. The scope of inspection covered fire detection systems, portable firefighting equipment, emergency egress routes, electrical safety observations, and staff fire-awareness readiness.

3. Inspection Checklist Summary

Item	Standard Requirement	Observed Status
Fire extinguishers	Serviced and tagged within last 12 months	Compliant at time of inspection
Emergency exit signage	Illuminated, visible from all work areas	Compliant
Emergency exit doors	Unobstructed, outward-opening, panic bar functional	Compliant at time of inspection
Fire alarm / detection system	Functional, tested quarterly	Functional — last test 28 Apr 2025
Emergency lighting	Operational on battery backup	Compliant
Electrical panel access	Clear 3-ft clearance maintained	Compliant
Fire assembly point	Marked, outside building, accessible	Compliant
Staff fire drill records	Conducted at least twice annually	Last drill: 02 Mar 2025

4. Findings and Observations

At the time of inspection, all fire safety systems and equipment were found to be in satisfactory working condition. Extinguishers across both floors carried valid service tags dated within the preceding six months. Emergency exit routes on the ground floor Sewing Hall were unobstructed at the time of inspection. The inspecting officer noted general good housekeeping standards in the Cutting Section and Finishing departments.

One minor observation was raised regarding storage practices near the rear stairwell on the first floor, where fabric roll storage was noted to be encroaching on the designated 1-metre clearance zone. This was flagged as a minor, non-blocking observation for facility management's attention and was not treated as a fail condition at time of inspection, given the egress path itself remained clear.

5. Recommendations

- Maintain the 1-metre clearance zone around the rear stairwell storage area on an ongoing basis
- Continue bi-annual fire drill schedule and retain attendance records for all shifts
- Re-verify extinguisher service tags on a rolling 6-month internal check, ahead of the annual formal inspection
- Ensure emergency lighting battery backup is tested monthly and logged

6. Certificate Validity Statement

This certifies that the above facility's fire extinguishers, emergency lighting, and evacuation signage were inspected and found satisfactory on the inspection date noted in Section 1. In accordance with Punjab Civil Defence regulations, this certificate remains valid for a period of 12 months from the date of issue. Renewal inspection must be completed and a new certificate issued before the expiry date to maintain valid certification status. Operating past the certificate's expiry date without a renewed inspection may result in non-compliance findings during third-party buyer audits (WRAP, BSCI, SMETA).

Reference note for audit cross-check: as of the current audit date, this certificate is more than 14 months past its stated validity period and has not yet been renewed.

Appendix A — Extinguisher Location Register (Ground Floor, extract)

Unit ID	Location	Type	Last Service Tag
FE-GF-01	Sewing Hall B, near Fire Exit	ABC Dry Powder	18 Nov 2024
FE-GF-02	Cutting Section entrance	CO2	18 Nov 2024
FE-GF-03	Finishing department	ABC Dry Powder	18 Nov 2024
FE-GF-04	Packing / dispatch area	ABC Dry Powder	18 Nov 2024

Appendix B — First Floor Extinguisher & Signage Register

Unit ID	Location	Type	Last Service Tag
FE-1F-01	Stairwell landing (rear)	ABC Dry Powder	18 Nov 2024
FE-1F-02	First floor sewing area	ABC Dry Powder	18 Nov 2024
FE-1F-03	First floor storage room	CO2	18 Nov 2024
ES-1F-01	First floor main exit	Illuminated exit sign	Functional
ES-1F-02	Rear stairwell exit	Illuminated exit sign	Functional

Appendix C — Risk Rating Matrix Used for This Inspection

Rating	Description	Action Required
Pass	Meets requirement, no action needed	None
Minor observation	Meets requirement, improvement noted	Address before next inspection
Fail — Minor	Does not meet requirement, low immediate risk	Correct within 30 days
Fail — Major	Does not meet requirement, immediate risk to occupants	Correct immediately

The rear stairwell storage observation noted in Section 4 was rated Minor Observation under this matrix, as the designated egress path itself remained clear at the time of inspection.

Appendix D — Facility Layout Notes for Inspection Reference

The ground floor houses the main Sewing Hall, Cutting Section, and the primary fire exit route leading to the outdoor assembly point at the north side of the plot. The first floor houses a secondary sewing area and general storage. Both floors are served by a single main stairwell and a secondary rear stairwell, the latter being the subject of the minor observation raised in Section 4. Inspectors are advised to check clearance around the rear stairwell specifically during the next scheduled visit.

Appendix E — Next Scheduled Actions

- Annual renewal inspection due: 12 May 2026
- Internal 6-month extinguisher tag self-check due: 12 Nov 2025
- Next scheduled fire drill (per bi-annual schedule): September 2025

Certified by: Fire Safety Inspector, Reg. No. FSI-0392 Signature: _____