Order Acknowledgement

Customer Information:

Faulty Material to be shipped to: ERICSSON INC C/O HWS

TELESUR

AMERRLC

HEILGENWEG 14 PARAMARIBO, SR SR

346 E. BELT LINE RD

SUITE 400

DOCK DOOR 40-42

COPPELL, TX 75019 USA

Contact: Roepnarain Boedhoe

For issues, please contact:
CUSTOMER INTERACTION CENTER

RMA Number: 1602938300 **Customer PO Number:** 4513524075

Customer RMA Reference:

Customer Place: SUR-001

Line	Created Date	Part Authorized	Alternate Part ID	Reference 1 / Reference 2 / Serial ID	Return Reason	Return Type	Declared Value	Scheduled Delivery Date	Line PO
1	11-Sep-17	UKL40170/A11 R6A		/ / A2310CV24L	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
2	11-Sep-17	UKL40170/A11 R6A		/ / A2310CZ7QE	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
3	11-Sep-17	UKL40170/A11 R6A		/ / A2310EX5SV	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
4	11-Sep-17	UKL40170/A11 R6A		/ / A2310CV7P9	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
5	11-Sep-17	UKL40170/A11 R6A		/ / A2310CV7QS	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
6	11-Sep-17	UKL40170/A11 R6A		/ / A2310CZ7GB	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
7	11-Sep-17	UKL40170/11 R6A		/ / A2310CLX9U	RPL-Repair And Replace	STD - Standard Repair	85 USD		4513524075
8	11-Sep-17	UKL40170/11 R6A		/ / A2310CM10Z	RPL-Repair And Replace	STD - Standard Repair	85 USD		4513524075
9	11-Sep-17	UKL40170/A13 R6A		/ / A2310DP7TS	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
10	11-Sep-17	UKL40170/A13 R6A		/ / A2310DP7HK	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075
11	11-Sep-17	UKL40170/13 R6A		/ / A2310CP4M8	RPL-Repair And Replace	STD - Standard Repair	266 USD		4513524075
12	11-Sep-17	UKL40170/13 R4A		/ / A231090QK4	RPL-Repair And Replace	STD - Standard Repair	266 USD		4513524075
13	11-Sep-17	UKL40170/A15 R6A		/ / A2310CZ7LE	RPL-Repair And Replace	STD - Standard Repair	233 USD		4513524075

Order Acknowledgement

14	11-Sep-17	UKL40170/A15 R6A	/ / A2310DSP5S	RPL-Repair And Replace	STD - Standard Repair	233 USD	4	513524075
15	11-Sep-17	UKL40170/A15 R6A	/ / A2310CZ7MD	RPL-Repair And Replace	STD - Standard Repair	233 USD	4	513524075
16	11-Sep-17	UKL40170/15 R6A	/ / A2310CM5PE	RPL-Repair And Replace	STD - Standard Repair	143 USD	4	513524075
17	11-Sep-17	ROJ2081308/4 R1D	/ / A2310DNHH4	RPL-Repair And Replace	STD - Standard Repair	132 USD	4	513524075
18	11-Sep-17	ROJ2081308/4 R1D	/ / A2310DNJNH	RPL-Repair And Replace	STD - Standard Repair	132 USD	4	513524075
19	11-Sep-17	ROJ2081308/4 R1D	/ / A2310DNHKM	RPL-Repair And Replace	STD - Standard Repair	132 USD	4	513524075