Order Acknowledgement

Customer Information:

Faulty Material to be shipped to:

TELESUR

AMERRLC

HEILGENWEG 14 PARAMARIBO, SR SR

346 E. BELT LINE RD

ERICSSON INC C/O HWS

SUITE 400

DOCK DOOR 40-42

COPPELL, TX 75019 USA

Contact: Roepnarain Boedhoe

For issues, please contact: CUSTOMER INTERACTION CENTER

RMA Number: 1602889328 **Customer PO Number:** 4513524075

Customer RMA Reference:

Customer Place: SUR-001

Line	Created Date	Part Authorized	Alternate Part ID	Reference 1 / Reference 2 / Serial ID	Return Reason	Return Type	Declared Value	Scheduled Delivery Date	Line PO
1	24-May-17	UKL40170/17 R6A		/ / A2310CVL08	RPL-Repair And Replace	STD - Standard Repair	280 USD		4513524075
2	24-May-17	UKL40170/17 R6A		/ / A231080NJX	RPL-Repair And Replace	STD - Standard Repair	280 USD		4513524075
3	24-May-17	UKL40170/A17 R6A		/ / A2310CP42S	RPL-Repair And Replace	STD - Standard Repair	255 USD		4513524075
4	24-May-17	UKL40170/A17 R6A		/ / A2310CVKGM	RPL-Repair And Replace	STD - Standard Repair	255 USD		4513524075
5	24-May-17	UKL40170/A17 R6A		/ / A2310CY97C	RPL-Repair And Replace	STD - Standard Repair	255 USD		4513524075
6	24-May-17	UKL40170/17 R6A		/ / A2310DP89D	RPL-Repair And Replace	STD - Standard Repair	280 USD		4513524075
7	24-May-17	UKL40170/17 R6A		/ / A231080XRU	RPL-Repair And Replace	STD - Standard Repair	280 USD		4513524075
8	24-May-17	UKL40170/17 R4A		/ / A231090PLW	RPL-Repair And Replace	STD - Standard Repair	280 USD		4513524075

