


SMT Side of Board

INSTRUCTIONS:

- 1. Cut foils at each point marked with RED
- 2. Connect insulated wires as shown in **GREEN**



DISPLAY Side of board