

INSTRUMENT APPROACH CHART



INSTRUMENT APPROACH CHART



In case of GO AROUND, pilot should report ATC as soon as practicable. Until receiving ATC instructions, aircraft turn left HDG 229° for joining HME R177 and missed approach procedure.