

## **INSTRUMENT APPROACH CHART**



## **INSTRUMENT APPROACH CHART**





In case of GO AROUND, pilot should report ATC as soon as practicable.

Until receiving ATC instructions, aircraft turn left HDG  $229^{\circ}$  for joining HME R177 and missed approach procedure.