

## **INSTRUMENT APPROACH CHART**



## **INSTRUMENT APPROACH CHART**



In case of GO AROUND, pilot should report ATC as soon as practicable.

Until receiving ATC instructions, aircraft turn left HDG 229° for joining HME R177 and missed approach procedure.