AERODROME ADVISORY CHART

Advisory 4

Pilots taxiing on TWY V are to maintain a lookout to ensure sufficient wing tip clearance

Advisory 1

Pilots taxiing on TXL R4 are to maintain a lookout to ensure sufficient wing tip clearance

Advisory 2

Pilots taxiing on TWY T are to maintain a lookout to ensure sufficient wing tip clearance

Advisory 3

Pilots taxiing on TWY N or P to holding point T1 or T2 via TWY T are to pay extra attention to ground signages and lightings to prevent the mistaken identification of TWY T as RWY 20C

Changes : Updated TWY M4 and M5 alignment.