	Vaehwardt Rivan &		
	1BM1905187 Date:	1	1
	Derive a Stepper Motor interface to rotate motor in clockwise by Msteps. Intro suitable de successive steps.	the	b (w
Ş			
	#include <reg51.h></reg51.h>		
	charxdata port_at_0xe803;		
	charrodata porta_at_0xe800;		
	charidataacc_at_0x30;		
	delay () Adelay b/w the rotation of the	<u>S. Y</u>	Notox
	for (j = 0; 3 < 800; j++)		
	for (j = 0,92800, j + 1)		
ORD.			
	void main()		
	5		
	port = 0x80; // config'all the ports of 80	55	as
	ushile (1)		
	}		
	acc = 0x88;		
	port a = acc;		

```
acc = 0 x 44;
porta = acc;
delay ();
acc = 0x22;
porta = acc;
delay ();
 acc = 0x111;
porta = acc;
delay();
```