Ex.No.-1.1-Design and Draft the given 2D Sketches in modelling software.

AIM

To sketch the given drawing with dimensions using fusion 360 tool.

REQUIREMENTS

Autodesk fusion 360


Windows 10

16 GB of RAM (integrated graphics recommend 2 GB or more)


2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE


1. Open new file and then select sketch icon.
2. Select the plane for sketching.
3. Use sketching features (line, circle, arc, rectangle, polygon, etc.,) to draw the given sketch




4. Use sketch modifying features (cut, trim, mirror, move, etc.,) to edit the sketch.




5. Use inspect feature to measure the dimensions of sketch.




6. After finishing the sketch use finish sketch option to finalize the sketch.




7. After finishing the sketch switch to drawing mode to plot the sketch in ISO standard.







SKETCHS


Ø20
Ø32
R64
R64
65
Ø40
Ø66
R6
R20
26
R7
R10
R10
R20
24
Ø20
Ø10
47
47

OUTPUT


Ø128.00
95.00
26.00
47.00
47.00
Linetype
Look At
Snap
Slice
Profile
Points
Dimensio
Constrain
Projected
Construct
3D Sketch



RESULT

Thus the given sketch is drawn and drafted using fusion 360 tool.