

-: connect	OUT: Single bus digital	+: Connect 3.3V, 5V
GND	signal output	+. Connect 3.3v, 3v
Range	Humidity: 20-90%RH	Temperature: 0~50 ℃
Accuracy	Humidity: ±5%RH	Temperature: ±2℃
Resolution	Humidity: 1%RH	Temperature: 1 $^{\circ}$ C

DHT11 is a temperature and humidity sensor. Its accuracy range, humidity: + -5% RH, temperature: + -2  $^{\circ}$ C. Measuring range, humidity: 20-90% RH, temperature: 0  $^{\circ}$  50  $^{\circ}$ C.