

Transfer of fixed z=0 calibration to other positions
Held-out LRM; all fits use the first-half 25-80 Hz band. At z=0, own and transfer values coincide.
Recorded command coordinates; auxiliary direct-target diagnostic. Cross-position checks are not independent repeat experiments.
D0: fit each position
D0: reuse z=0
D2: fit each position
D2: reuse z=0
Logical inputs to nullspace output
Nullspace input to logical outputs
25-80 Hz held-out response RMS / same-position B0
Evaluation position z (mm)
0
0.1
0.2
0.3
0.4
0.5
0.6
0.7
0.8
0.9
1
-0.5
0
0.5
1