

VMC Lite-1 — Operation & Maintenance Manual

Overview

Compact VMC for prototyping and small batch runs. Status IDLE when not in production schedule.

Safety

Single-operator station. Maximum workpiece weight: 50 kg.

Startup

Warm spindle for 5 minutes before full-speed cutting. Verify workholding before each job.

Idle Mode

When idle, run weekly spindle rotation (10 min at 1000 RPM) to prevent bearing brinelling.

Emergency Contacts

- 1 Maintenance Lead: ext. 204
- 2 Plant Manager: ext. 101
- 3 Safety Officer: ext. 999