


Figure 1. Portions of the fuel servo throttle arm and associated hardware as received.




Figure 2. Two portions of the throttle arm with a fractured threaded section.