

FIELD SERVICE REPORT

FSR NO. 020088970

SOFTWARE HARDWARE	OTHERS .
Customer: MDC 1136	Time Arrived: 2:42 PM Date Attended: 1-4-25
Address: Muntinlupa (it Alala Malls Southpark	Time Started: 2.42 pm Time Ended: 4.00 pm
Contact Person :	
Unit / Description :	INCIDENT No.: PLS-20250104-201689
Nature of Call/Problem:	Units/Materials Complete Details :
IOS #6 CPU emits roisy sound	
Actions Taken:	
Cleaned power supply Tested and Observe	X .
Fan Still emits noise	
13/A 3/H 21/12/20	
Status: For Replacement Request	
3	
	m.
Sporter	150 RMAS 1=4-25
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name