Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-18T00:00:00Z Currency: USD

Total Project Cost: USD 1,619.76

Estimate reasoning

Image shows active/standing water at the shower threshold with compromised seal/grout. Industry standard actions: replace shower door assembly if threshold seal is failed (R&R; Shower door - High grade), regrout tile joints around threshold (Tile shower - regrout), and install/repair hot mop shower pan membrane under tile to stop subfloor infiltration. Include heavy cleaning/corrosion mitigation for exposed hardware.

ID	Item	Qty	Unit	Unit Price	Tax	Total	Category
1	R&R Shower door - High grade	1	USD 939.9 6	USD 41.97	USD 981.93	Shower	
2	Tile shower - regrout	1	USD 225.5 4	USD 1.32	USD 226.86	Tile	
3	Shower pan - hot mop - 17 to 30 SF	1	USD 386.9 6	USD 1.62	USD 388.58	Shower	
4	Clean shower door - Heavy	1	USD 30.55	USD 1.84	USD 32.39	Cleaning	

Appendix: Item Details

1 — R&R; Shower door - High grade

Replace shower door assembly due to water intrusion at threshold and seal failure; high grade unit selected for durability.

2 — Tile shower - regrout

Regrout affected tile joints at shower curb and adjacent floor to restore water-tightness and prevent further seepage.

3 — Shower pan - hot mop - 17 to 30 SF

Install hot mop shower pan membrane under tile where water intrusion likely occurred; assumes removal of damaged underlayment and reinstall.

4 — Clean shower door - Heavy

Heavy cleaning and corrosion mitigation for surrounding hardware and glass due to prolonged water exposure.

Tags: corrosion_mitigation