Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-18T00:00:00Z Currency: USD

Total Project Cost: USD 2,352.17

Estimate reasoning

Scope addresses water intrusion through damaged roof sections and resultant bathroom water damage. Roofing line items are replaced where materials are missing/compromised; interior finishes are selectively removed and replaced with MR drywall, finished, primed, and painted. Toilet is reset with new seal for access and sanitary reconnection. Quantities are based on visible affected areas: approximately 7 SQ of roofing repair, 20 SF of lower-wall drywall replacement, 40 SF of paint/prime blending, and 60 SF antimicrobial treatment including subfloor/tub side.

ID	Item	Qty	Unit	Unit Price	Tax	Total	Category
RF G-0 01	Tear off, haul and dispose of comp. shingles - Laminated	7	USD 52.56	USD 0.00	USD 367.92	Roofing	
RF G-0 02	Laminated - comp. shingle roofing - w/out felt	7	USD 153.1 1	USD 0.00	USD 1 ,071.7 7	Roofing	
RF G-0 03	Roofing felt - 15 lb.	7	USD 18.00	USD 0.00	USD 126.00	Roofing	
RF G-0 04	Ice & water shield	120	USD 1.02	USD 0.00	USD 122.40	Roofing	
RF G-0 05	Continuous ridge vent - shingle-over style	20	USD 5.37	USD 0.00	USD 107.40	Roofing	
RF G-0 06	Ridge cap - composition shingles	20	USD 3.19	USD 0.00	USD 63.80	Roofing	
RF G-0 07	Flashing - pipe jack	2	USD 20.85	USD 0.00	USD 41.70	Roofing	
INT- 001	R&R Toilet	1	USD 541.5 3	USD 19.65	USD 561.18	Plumbing	
INT- 002	Drywall remove (damaged up to 2 ft)	20	USD 2.25	USD 0.00	USD 45.00	Demolition	
INT- 003	Drywall install MR 1/2"	20	USD 3.00	USD 0.00	USD 60.00	Drywall	
INT- 004	Tape & float L4	20	USD 1.50	USD 0.00	USD 30.00	Drywall	
INT- 005	Prime stain-blocker	40	USD 0.60	USD 0.00	USD 24.00	Painting	
INT- 006	Paint wall (2 coats)	40	USD 1.40	USD 0.00	USD 56.00	Painting	

ID	Item	Qty	Unit	Unit Price	Tax	Total	Category
MIT -001	Antimicrobial treatment	60	USD 0.75	USD 0.00	USD 45.00	Mitigation	

Appendix: Item Details

RFG-001 — Tear off, haul and dispose of comp. shingles - Laminated

Selective tear-off in affected slopes for water intrusion repair. Quantity rounded to nearest SQ for work area shown.

Tags: tearoff, disposal | Source: file: KB_Roofing.csv, page: 1

RFG-002 — Laminated - comp. shingle roofing - w/out felt

Install laminated shingles in repair area to restore watertight envelope.

Tags: shingle, roof | Source: file: KB_Roofing.csv, page: 1

RFG-003 — Roofing felt - 15 lb.

Underlayment replacement in torn/exposed areas prior to shingle install.

Tags: felt, underlayment | Source: file: KB_Roofing.csv, page: 1

RFG-004 — Ice & water shield

Install self-adhered membrane at repair transitions, ridge, and around penetrations observed.

Tags: waterproofing, membrane | Source: file: KB_Roofing.csv, page: 1

RFG-005 — Continuous ridge vent - shingle-over style

Replace damaged section of shingle-over ridge vent visible in photo.

Tags: ridgevent, vent | Source: file: KB_Roofing.csv, page: 1

RFG-006 — Ridge cap - composition shingles

Replace ridge caps removed/damaged with ridge vent work.

Tags: ridgecap, shingle | Source: file: KB_Roofing.csv, page: 1

RFG-007 — Flashing - pipe jack

Replace deteriorated neoprene pipe boots at penetrations in repair area.

Tags: flashing, pipe | Source: file: KB_Roofing.csv, page: 1

INT-001 — R&R; Toilet

Detach and reset toilet to access/repair wet flooring; includes new wax ring/seal.

Tags: toilet, replace | Source: file: KB_Example_Macro.csv, page: 1

INT-002 — Drywall remove (damaged up to 2 ft)

Selective demolition of water-stained lower wall areas at bathroom perimeter, up to 2 ft.

Tags: drywall, remove | Source: file: KB_Example_Macro.csv, page: 1

INT-003 — Drywall install MR 1/2"

Install moisture-resistant drywall at removed sections.

Tags: drywall, install | Source: file: KB_Example_Macro.csv, page: 1

INT-004 — Tape & float L4

Finish new drywall to match existing texture level 4.

Tags: drywall, finish | Source: file: KB_Example_Macro.csv, page: 1

INT-005 — Prime stain-blocker

Prime repaired wall sections to block water stains and prep for paint. Includes blend to nearest break.

Tags: primer, stain | Source: file: KB_Example_Macro.csv, page: 1

INT-006 — Paint wall (2 coats)

Paint repaired bathroom wall areas, two coats, color match.

Tags: paint, wall | Source: file: KB_Example_Macro.csv, page: 1

MIT-001 — Antimicrobial treatment

Treat exposed subfloor and framing at toilet and tub side where water pooled.

Tags: antimicrobial | Source: file: KB_Example_Macro.csv, page: 1