Insurance Damage Estimate

Version: 1.0 Generated: 2025-08-18T12:00:00Z Currency: USD

Total Project Cost: USD 1,954.17

Estimate reasoning

Image shows a fractured and heavily soot-stained toilet bowl with heat deformation and significant soot on stall partition and adjacent finishes. The toilet is non-repairable and requires full replacement. The stall partition is warped from heat and should be replaced with a high-grade partition. Heavy cleaning is required for residual soot and fire residue on tile and floor surfaces. Quantities set to one each for a single-stall restroom; selected line items come from the provided pricing catalogue.

ID	Item	Qty	Unit	Unit Price	Tax	Total	Category
			USD 541.5		USD		
1	R&R Toilet	1	3	USD 19.65	561.18	plumbing	
2	R&R Toilet partition - High grade (i.e., phenolic, etc.)	1	USD 1,297 .52	USD 53.70	USD 1 ,351.2 2	partitions	
3	Clean toilet - Heavy	1	USD 39.41	USD 2.36	USD 41.77	cleaning	

Appendix: Item Details

1 — R&R; Toilet

Toilet bowl fractured, heavily sooted and burned — full replacement required.

Tags: replace, toilet, fire-damage | Source: file: Pricing Catalogue (excerpt), page: 1

2 — R&R; Toilet partition - High grade (i.e., phenolic, etc.)

Partition panel warped/melted by heat and soot penetration; full replacement of stall partition recommended.

Tags: replace, partition, fire-damage | Source: file: Pricing Catalogue (excerpt), page: 1

3 — Clean toilet - Heavy

Heavy soot and residue on adjacent tile and floor surfaces; heavy cleaning of stall and fixtures after removal/replace.

Tags: repair, cleaning, fire-residue | Source: file: Pricing Catalogue (excerpt), page: 1