102001208 ENGINEERING GRAPHICS

Orthographic Projection

Outline

- ◆Introduction Sectional View
- Sectional Views Steps
- ♦ Section Lines Rules
- Solution of Problems-Sectional View

INTRODUCTION - SECTIONAL VIEWS

The purpose of drawing a sectional view

(1) If the object is simple, the dotted lines will be very few. However, if it is complex, there will be too many dotted lines. It will be difficult to interpret each and every dotted line. Hence a sectional view is drawn to avoid excessive dotted lines.

INTRODUCTION - SECTIONAL VIEWS

The purpose of drawing a sectional view

(2) A sectional view clearly shows the internal details of the object.

The object is imagined to be cut by a cutting plane.

The part of the object, in-between the observer and the cutting plane, is imagined to be discarded.

The view of the remaining object is drawn and it is called a <u>sectional</u> <u>view</u>.

Thus, there can be a <u>sectional front</u> <u>view</u>, a <u>sectional top view</u> or a <u>sectional side view</u>.

Section lines OR hatching lines are drawn in those areas, where the material is cut.

The other views are unaffected by the use of the cutting plane.

The cutting plane is shown as a centre line and the ends are made thicker.

The position of the cutting plane should be shown on the appropriate view.

SECTION LINES (or HATCHING LINES)

Section lines should be shown

in the area where the material

of the object is cut.

SECTION LINES (or HATCHING LINES)

Section lines should be thin, medium dark, at 45° to the horizontal, and spaced uniformly about 2 or 3 mm apart, as shown below.

2 OR 3 mm


SPECIAL RULES - SECTION LINES


Thin plates, which are used to give additional strength to the object, are called RIBS (or WEBS). They may be triangular, rectangular etc.

SPECIAL RULES - SECTION LINES

If a rib is cut longitudinally, (i.e. dividing the thickness), the section lines are not shown in the rib area.

If a rib is cut perpendicularly (or at right angles to its thickness), section lines are shown in the cut portion (cut area) of the rib.






THE RIB IS CUT AT RIGHT ANGLES TO ITS PLANE (PERPENDICULARLY).
HENCE SECTION LINES ARE SHOWN IN THE CUT PORTION OF THE RIB.


SPECIAL RULES - SECTION LINES


Many machine parts such as nuts, bolts etc. <u>are not shown in section</u>, if the <u>cutting</u> <u>plane passes through their axes.</u> Such parts are – bolts, nuts, studs, spindles, shafts, cotters, keys, rivets, set screws etc.


However, if they are cut perpendicular to their axes, then the <u>section lines are shown in the cut surface.</u>


PROBLEM SOLUTION












































































3-D 1058-B
































































Draw the sectional front view.


















Draw the sectional front view.








Draw the sectional top view.





Practice Problem:-

Draw the sectional front view.

