
1. Since the DRV8835 motor driver chip and MPU6050 gyro module are temporarily out-of-stock, we use the TB6612 motor driver chip and the QMI8658C gyro module to replace them.


Therefore, in the folder for the main program, you need to select the correct program according to the type of driver chip and the gyro module on the expansion board.

ame	Date modified	Туре	Size	
DRV8835	3/16/2021 5:34 PM	File folder		
TB6612 & MPU6050	3/16/2021 5:34 PM	File folder		
TB6612 & QMI8658C	12/15/2021 5:27 PM	File folder		7

2. The chip inside the red rectangle in the picture below is the TB6612 motor driver chip.



3. The chip inside the red rectangle in the picture below is the DRV8835 motor driver chip.



4.The silkscreen on the QMI8658C module and MPU6050 module is different, you can identify the chip by the silkscreen in the pictures below.

QMI8685C gyro module



MPU6050 gyro module

