FICTIONAL SAMPLE MANUAL - FOR DEMO ONLY

NovaFlow Medical (fictional manufacturer)

Model IP-200 Volumetric Infusion Pump

Service & Troubleshooting Guide, Rev. A (synthetic)

This document is synthetic and not a real manufacturer manual.

It exists only to demonstrate MedTrace AI evidence retrieval.

Section 2 - Safety Warnings

WARNING: Only qualified biomedical engineering staff may service the IP-200.

WARNING: Follow your facility's procedures for equipment in clinical use.

CAUTION: Do not attempt internal repairs while the device is in clinical use.

Record all alarm events in the facility equipment log.

Section 5 - Alarm and Error Codes

E-101 Air-in-line detected. Refer to Section 6.2.

E-102 Door open. Verify the pump door latch is fully closed.

E-104 Downstream occlusion. Pressure exceeded the downstream limit.

Possible causes: closed clamp, kinked tubing, filter blockage.

Escalate repeated E-104 alarms to biomedical engineering.

E-110 Battery low. Connect to mains power per facility policy.

E-199 Internal system fault. Remove from service and contact technical support.

Section 6 - Troubleshooting

6.1 Occlusion alarms (E-104): The downstream pressure sensor reports pressure above threshold. Inspect the administration set for kinks and clamps per facility protocol. If the alarm recurs after the set is checked, tag the pump and send to biomedical engineering for a pressure sensor calibration check (Service Procedure SP-12).

6.2 Air-in-line (E-101): Refer to clinical protocol for line priming.

Section 9 - Service Contact

For E-199 or unresolved alarms, contact NovaFlow Technical Support (fictional) with model number, serial number, and the error log export. Serial numbers are located on the rear label, format NF-IP2-XXXXX.