School Facilities and Organization

INFORMATION AND CONDITION OF SCHOOLS

Asset Preservation Program Annual Board Report (Vancouver School District)

SITE	BUILDING	BUILDING BOARD ACCEPTANCE DATE	APP YEAR	-------2024-2025------- BUILDING CONDITION ASSESSMENT %	ANNUAL REVIEW COMPLETED BY	NEXT CERTIFIED BCA DUE
Roosevelt Elementary School	Main Building	1/10/1994	30	87.62	District	2026
Harney Elementary School	Main Building	4/30/1997	27	87.83	District	2026
Sarah J. Anderson Elementary School	Main Building	8/8/2005	19	94.69	District	2026
Lake Shore Elementary School	Main Building	3/13/2000	25	93.83	District	2026
Salmon Creek Elementary School	Main Building	6/13/2005	19	91.55	District	2026
Minnehaha Elementary School	Main Building	2/28/2000	25	84.98	District	2026
Dwight D. Eisenhower Elementary School	Main Building	12/10/2007	17	93.62	District	2026
Lincoln Elementary School	Main Building	4/30/1997	27	77.23	District	2027
Skyview High School	Main Building	4/27/1998	26	88.43	District	2028
Washington Elementary School	Main Building	11/8/2004	20	88.22	District	2028
Hazel Dell Elementary School	Main Building	3/24/2004	21	87.37	District	2028
Fruit Valley Elementary School	Main Building	6/9/2003	21	87.56	District	2028
Benjamin Franklin Elementary School	Main Building	6/28/2004	20	89.57	District	2028

Roosevelt Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Single Story
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	1/10/1994
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	30	87.62	District	Not Reported
2023-2024	30	87.62	District	4/9/2024
2022-2023	29	87.62	District	3/14/2023
2021-2022	28	87.62	District	2/8/2022
2020-2021	27	87.62	Consultant	2/9/2021
2019-2020	26	89.20	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1992	001	14,966	14,966	14,966		
1992	007	11,687	11,687	11,687		
1992	005	10,957	10,957	10,957		
1992	006	10,934	10,934	10,934		
1992	002	7,082	7,082	7,082		
1992	011	6,114	6,114	6,114		
1992	004	4,325	4,325	4,325		
1992	003	2,050	2,050	2,050		
1992	014-Covered Play	1,800	1,800	900		

1995	015	6,917	0	0
2014	010	2,776	2,776	2,776
2014	009	2,772	2,772	2,772
2014	008	2,729	2,729	2,729
	Building Totals	**85,109**	**78,192**	**77,292**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: Outside areas against walls & windows outside room 2&3 Deficiency: Trees planted too close to outside walls and in front of office.		
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Roof Construction	B1020		62.00% Fair
	Deficiencies:	Leaking		
	Causes:	Other		
	Comments:	Location: soft areas by ladder outside hatch over music room. Some rot around & under eves		
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Deficiencies:	Efflorescence and Staining		
	Causes:	Other, Surface Damage		
	Comments:	age of school		
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		90.00% Good
	Deficiencies:	Leaking, Other, Sagging		
	Causes:	Faulty Design, Standing Water		
	Comments:	Location: By each roof drain and under eves Deficiency: Puddling and rot in eves		
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good
	Deficiencies:	Other		
	Causes:	Surface Weathering		
	Comments:	skylights are decolored		
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		62.00% Fair
	Deficiencies:	Other, Stains, Discoloration		
	Causes:	Deterioration		
	Comments:	age of flooring		
	Ceiling Finishes	C2050		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Sanitary Drainage	D2020		90.00% Good
	Building Support Plumbing Systems	D2030		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Comments:	Location: Boiler room		
	Cooling Systems	D3030		90.00% Good
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electronic Safety and Security	*Comments:*	All New Cameras 2019, New Thermo camera in front entry 2021		
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Comments:	New Refrigeration Freezer system 2019		
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good

Harney Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	4/30/1997
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	27	87.83	District	Not Reported
2023-2024	26	87.83	District	4/9/2024
2022-2023	25	87.81	District	3/14/2023
2021-2022	24	89.87	District	2/8/2022
2020-2021	23	89.87	Consultant	2/9/2021
2019-2020	22	89.87	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1996	008	17,333	17,333	17,333		
1996	005	9,084	9,084	9,084		
1996	004	9,084	9,084	9,084		
1996	001	8,520	8,520	8,520		
1996	003	8,520	8,520	8,520		
1996	007	6,812	6,812	6,812		
1996	002	4,305	4,305	4,305		
1996	006	3,034	3,034	3,034		
	Building Totals	**66,692**	**66,692**	**66,692**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
	Deficiencies:	Cracking, Surface Deterioration		
	Causes:	Soils		
	Comments:	Deficiency: some spalling/cracking where foundation is visible		
Slabs on Grade	Standard Slabs on Grade	A4010		100.00% Excellent
	Pits and Bases	A4040		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent
Superstructure	Floor Construction	B1010		100.00% Excellent
	Roof Construction	B1020		100.00% Excellent
	Stairs	B1080		100.00% Excellent
Exterior Vertical Enclosures	Exterior Walls	B2010		62.00% Fair
	Deficiencies:	Cracking, Peeling, Flaking, Efflorescence and Staining, Other		
	Causes:	Other, Surface Damage		
	Comments:	Deficiency: efflorescence at some brick @ gym interior. limited staining on brick. EIFS is showing its age, some discoloration, staining and some cracking. some control joint mat'l missing. some joints material pulling away/shrinkage. Corrective Actions: fill missing control joint mat'l, apply sealant where needed. Additional: EIFS is dented in multiple locations (suspect dents are from balls?) patched but visible		
	Exterior Windows	B2020		90.00% Good
	Deficiencies:	Other		
	Causes:	Caulking/Weather Stripping, Material Condition, Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	*Comments:*	Deficiency: a couple of windows at stair exits appear to have broken seals (condensation)		
	Exterior Doors and Grilles	B2050		90.00% Good
	Comments:	These were showing wear but were repainted 2021		
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		62.00% Fair
	Deficiencies:	Leaking, Other		
	Causes:	Cracks, Tears, Holes, and Breaks, Surface Weathering		
	Comments:	Deficiency: membrane roof still in good condition. metal roofing starting to show age, discoloration and minor rust spots. Additional: staff reported no major leaking. occasional minor leaks have been repaired through work orders. 2022, Many roof leaks in FCRC area, 211, 116, 210		
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Deficiencies:	Peeling Paint or Delamination		
	Causes:	Material Condition, Other		
	Comments:	Restroom partitions need painting.		
	Interior Grilles and Gates	C1040		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Construction	Raised Floor Construction	C1060		100.00% Excellent
	Suspended Ceiling Construction	C1070		100.00% Excellent
Interior Finishes	Wall Finishes	C2010		62.00% Fair
	Deficiencies:	Surface Appearance		
	Causes:	Maintenance, Other		
	Comments:	Classrooms needing paint, showing patches of repairs Hallways painted 2017-2018 Repairs needed because of roof leaks.		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		90.00% Good
	Comments:			
	Stair Finishes	C2040		62.00% Fair
	Deficiencies:	Irregular Surface, Other, Stains, Discoloration		
	Causes:	Deterioration, Other		
	Comments:	Deficiency: rubber treads/risers at exit stairs showing age. flooring at base has gaps, especially at thresholds. Walk off matting has been replaced.		
	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		100.00% Excellent
Plumbing	Domestic Water Distribution	D2010		100.00% Excellent
	Deficiencies:	Discolored Fixtures, Other, Pressure Loss		
	Causes:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Plumbing	*Comments:*	Deficiency: poor water pressure; hot water heaters reaching end of life cycle Corrective Actions: replace hot water heaters Additional: poor water pressure appears to be result of city water in this area, as opposed to bldg design 2017: Gang restrooms in pods sinks showing rust on piping. Inside main urinals.		
	Sanitary Drainage	D2020		100.00% Excellent
	Building Support Plumbing Systems	D2030		100.00% Excellent
HVAC	Facility Fuel Systems	D3010		100.00% Excellent
	Comments:	Natural gas meter inspected August 2021		
	Heating Systems	D3020		90.00% Good
	Comments:	Boilers replaced 2017/2018.		
	Cooling Systems	D3030		62.00% Fair
	Deficiencies:	Other, System Inefficient		
	Causes:	Equipment Obsolescence, Other		
	Comments:	Deficiency: equipment worn but reliable; moving parts starting to wear; availabilty of parts sometimes an issue. 2021 A couple of heat pumps were replaced.		
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Comments:	New FA Panel 2019		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Fire Protection	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Electrical Services and Distribution	D5020		100.00% Excellent
	General Purpose Electrical Power	D5030		100.00% Excellent
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		100.00% Excellent
	Voice Communications	D6020		100.00% Excellent
	Audio-Video Communications	D6030		100.00% Excellent
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Electronic Surveillance	D7030		100.00% Excellent
	Detection and Alarm	D7050		100.00% Excellent
Integrated Automation	Integrated Automation Facility Controls	D8010		100.00% Excellent
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Comments:	Rubberized surface added for playground fall zones. 2017/2018		
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		62.00% Fair
	Deficiencies:	Other		
	Causes:	Deterioration		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Furnishings	*Comments:*	Some showing wear from moving over the years.		

Lincoln Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	4/30/1997
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	27	77.23	District	Not Reported
2023-2024	26	77.23	District	4/9/2024
2022-2023	25	77.23	District	3/14/2023
2021-2022	24	75.18	Consultant	2/8/2022
2020-2021	23	83.16	District	2/9/2021
2019-2020	22	83.16	District	2/18/2020

The next certified BCA is due: 2027

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1996	008	17,571	17,571	17,571		
1996	004	9,093	9,093	9,093		
1996	006	9,088	9,088	9,088		
1996	003	8,522	8,522	8,522		
1996	001	8,518	8,518	8,518		
1996	007	6,778	6,778	6,778		
1996	002	4,306	4,306	4,306		
1996	005	3,024	3,024	3,024		
	Building Totals	**66,900**	**66,900**	**66,900**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
	Deficiencies:	Cracking		
	Comments:	Deficiency: minor spalling, cracks where exposed outside.		
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Comments:	Location: Cafeteria, 5th grade pod Deficiency: Some settling, tiles have been replaced, Corrective Actions: Work orders & inhouse repairs		
	Pits and Bases	A4040		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Floor Construction	B1010		90.00% Good
	Roof Construction	B1020		90.00% Good
	Deficiencies:	Adhesion, Bare Areas, Fastening Failure, Leaking		
	Causes:	Other		
	Comments:	Location: Gym Deficiency: Roof on gym is puffy at SE corner. Have had several leaks this past year.		
	Stairs	B1080		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		62.00% Fair
	Deficiencies:	Cracking, Peeling, Flaking, Damaged Masonry, Efflorescence and Staining		
	Causes:	Other, Surface Damage		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	*Comments:*	Location: Control Joint @ playground wall between boiler room and electrical room. Misc. locations for other issues. Deficiency: Missing control joint material near playground, bottom vertical bricks are broken at control joint. Some sealant joints have separated or caulking has aged (i.e. where wall material changes such as EIFS/brick or EIFS/metal) EIFS is looking worn/weathered/stained in places; limited cracks at windows. Corrective Actions: fill control joint. re-caulk other joints that may have separated. Additional: limited staining on brick, esp. near sign at rear and at overflow drain locations No change since last review in 2016 (2021)		
	Exterior Windows	B2020		62.00% Fair
	Deficiencies:	Excessive Heat Loss, Other		
	Causes:	Material Condition, Other		
	Comments:	Location: At stairwell landings Deficiency: 8 windows ion North end have lost the air/gas seal, 5 windows on S end have moisture inside No Change since last review in 2016 (2021)		
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		62.00% Fair
	Deficiencies:	Other		
	Causes:	Material Condition		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	*Comments:*	due to age of finish - shows fading, stains		
Exterior Horizontal Enclosures	Roofing	B3010		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other, Surface Weathering		
	Comments:	Location: worst discoloration at areas where metal roof meets another material (like brick wall) Deficiency: finish of metal roofing panels starting to show age - some limited spots of rust, some staining/fading or moss discoloration Additional: Staff and maintenance reported no current issues with leaks. No change since last review in 2016 (2021)		
	Roof Appurtenances	B3020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Surface Weathering		
	Comments:	age of materials		
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		62.00% Fair
	Deficiencies:	Peeling Paint		
	Causes:	Surface Damage		
	Comments:	age of materials		
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Construction	Raised Floor Construction	C1060		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: School Stage Deficiency: A few dings in the wood floor, normal wear		
	Suspended Ceiling Construction	C1070		90.00% Good
Interior Finishes	Wall Finishes	C2010		62.00% Fair
	Deficiencies:	Other		
	Causes:	Moisture		
	Comments:	Location: restroom tile grout Deficiency: Some repaired damage at restrooms. no change since 2016 (2021)		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		90.00% Good
	Deficiencies:	Broken or Loose Tiles		
	Causes:	Other		
	Comments:	Location: Main entrance Deficiency: minor cracking in VCT Additional: flooring is aging, but overall in good condition Near end of useful life. New Carpet 2021		
	Stair Finishes	C2040		62.00% Fair
	Deficiencies:	Broken Treads, Other, Stains, Discoloration		
	Causes:	Deterioration, Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Comments:*	Location: both exit stair towers - rubber treads/risers main stairs - rubber treads/risers Deficiency: Rubber stair treads in aging poorly at stair towers, separating in places. Material aging better at main stairs, but separating in places. No change since 2016 (2021)		
	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		90.00% Good
	Comments:	Location: Elevator has been repaired.		
Plumbing	Domestic Water Distribution	D2010		62.00% Fair
	Deficiencies:	Lack of Water Flow		
	Causes:	Defective Back Flow Device, Defective Valves, Other		
	Comments:	Location: water heaters in main floor mechanical/boiler room Deficiency: poor water pressure; water heaters at end of their life cycle. Corrective Actions: water heaters ought to be replaced in near future Additional: Poor water pressure is result of poor water pressure in this part of town - not fault of bldg design Hot water sometimes finds it's way to cold water side - may be at custodial sinks where equipment is hooked in. should be investigated for cause and rectified. (2021)		
	Sanitary Drainage	D2020		90.00% Good
	Building Support Plumbing Systems	D2030		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	Heating Systems	D3020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Equipment Obsolescence, Other		
	Comments:	Location: Boiler room Deficiency: Out of 6 boilers, only 4 are operable. Corrective Actions: None needed at this time. Additional: Bldg does not need 6 to operate properly - capacity is more than sufficient with 4 (Comments by Maintenance Staff). System moving parts starting to wear out, and some parts are no longer available. Life Cycle for some equipment is reaching end through normal wear and tear. Age of system and change in controls for Covid-19 over pressurized large areas like to gym.		
	Cooling Systems	D3030		62.00% Fair
	Deficiencies:	Other		
	Causes:	Equipment Obsolescence, Other		
	Comments:	Deficiency: equipment worn but reliable and no reports of issues with cooling problems, but equipment is aging and has components that need repair from time to time. Additional: Life cycle and equipment obsolescence beginning to be an issue. Leaking Ball Valves need replaced, Rebuild kets no longer avail. Age of system (2021)		
	Facility HVAC Distribution Systems	D3050		62.00% Fair

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	*Deficiencies:*	Other		
	Causes:	Other		
	Comments:	Penthouses have insulation and vapor barrier falling down and should be re-secured for fresh air plenums.		
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	age of lighting		
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Integrated Automation	*Comments:*	age of controls		
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
	Deficiencies:	Other, Unsightly		
	Causes:	Deterioration		
	Comments:	Additional: general aging of equipment through normal wear and tear		
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good

Skyview High School - Main Building

Building Details

PROFILE TYPE	High School - Multi-Story
NUMBER OF FLOORS	3
BOARD ACCEPTANCE DATE	4/27/1998
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	26	88.43	District	Not Reported
2023-2024	25	88.43	District	4/9/2024
2022-2023	24	89.32	Consultant	3/14/2023
2021-2022	23	82.06	District	2/8/2022
2020-2021	22	83.59	District	2/9/2021
2019-2020	21	83.58	District	2/18/2020

The next certified BCA is due: 2028

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1997	010	21,449	21,449	21,449		
1997	009	16,576	16,576	16,576		
1997	026	16,191	16,191	16,191		
1997	024	16,063	16,063	16,063		
1997	002	15,975	15,975	15,975		
1997	025	15,941	15,941	15,941		
1997	011	15,136	15,136	15,136		
1997	018	14,095	14,095	14,095		
1997	016	13,637	13,637	13,637		

1997	017	11,929	11,929	11,929
1997	001	10,381	10,381	10,381
1997	031	9,928	9,928	9,928
1997	003	9,030	9,030	9,030
1997	021	8,283	8,283	8,283
1997	019	7,192	7,192	7,192
1997	022	7,178	7,178	7,178
1997	008	6,608	6,608	6,608
1997	007	5,361	5,361	5,361
1997	029	4,750	4,750	4,750
1997	006	4,678	4,678	4,678
1997	015	4,610	4,610	4,610
1997	032	3,631	3,631	3,631
1997	004	3,607	3,607	3,607
1997	030	3,561	3,561	3,561
1997	005	3,406	3,406	3,406
1997	027	3,024	3,024	3,024
1997	014	2,758	2,758	2,758
1997	028	2,666	2,666	2,666
1997	013	2,540	2,540	2,540
1997	012	2,497	2,497	2,497
1997	023	1,482	1,482	1,482
	Building Totals	**264,163**	**264,163**	**264,163**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Pits and Bases	A4040		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Floor Construction	B1010		90.00% Good
	Roof Construction	B1020		90.00% Good
	Stairs	B1080		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: Treads and concrete steps Deficiency: Some concrete cracks, treads loose or missing. Some corrections were made in 2018 on interior stairs w/ rubber tread.covers.		
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Deficiencies:	Rot or Corrosion		
	Causes:	Frame/Molding Condition, Other		
	Comments:	Deficiency: Entry Doors by gyn rusted out.		
	Exterior Louvers and Vents	B2070		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Some vents have rusted completely through		
Exterior Horizontal Enclosures	Roofing	B3010		90.00% Good
	Deficiencies:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	*Causes:*	Surface Weathering		
	Comments:	03/07/17 TPO has surface weathering and wear; some upper downspouts daylight onto TPO and cause degradation Saw no issues 2022.		
	Roof Appurtenances	B3020		90.00% Good
	Deficiencies:	Other		
	Causes:	Surface Weathering		
	Comments:	03/07/17 Peeling paint and flaking at multiple locations at downspouts and scuppers		
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Multiple windows have seals that have failed		
	Interior Doors	C1030		62.00% Fair
	Deficiencies:	Other		
	Causes:	Frame/Molding Condition, Material Condition		
	Comments:	Multiple doors are out of order and so not operate.		
	Interior Grilles and Gates	C1040		90.00% Good
	Comments:	Corrected 2020, adjustments still needed		
	Suspended Ceiling Construction	C1070		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Construction	*Comments:*	Repaired 2019		
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Comments:	Deficiency: Minimal wear. Corrective Actions: Was mostly repainted 2012/13		
	Interior Fabrications	C2020		90.00% Good
	Comments:	Railings refinished 2021		
	Flooring	C2030		90.00% Good
	Deficiencies:	Missing Grout, Other, Stains, Discoloration		
	Causes:	Deterioration, Missing Material, Other, Sealing		
	Comments:	New carpet summer 2022. Also rubber base. Gym floor was also redone. Grout and caulking needed in commons, upper gym floor needs repairs, and discolored VCT throughout building		
	Stair Finishes	C2040		62.00% Fair
	Deficiencies:	Irregular Surface, Stains, Discoloration		
	Causes:	Deterioration, Other		
	Comments:	03/07/17 Concrete stair treads have consistent cracks; some starting to chip out; railings need paint. Some repairs made 2019 Stable concrete cracking 2022. Railings need painted, stair coverings need repaired		
	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		90.00% Good
Plumbing	Domestic Water Distribution	D2010		62.00% Fair
	Deficiencies:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Plumbing	*Causes:*	Other		
	Comments:	Plumbing looked good and no complaints from maintenance.		
	Sanitary Drainage	D2020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	No complaints 2022 Age of system is 26 years.		
	Building Support Plumbing Systems	D2030		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Age of plumbing system is 26 years.		
	General Service Compressed-Air	D2050		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		100.00% Excellent
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	New boilers in 2022.		
	Cooling Systems	D3030		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	One chiller being replaced 2022.		
	Facility HVAC Distribution Systems	D3050		62.00% Fair
	Deficiencies:	Insufficient Air Flow		
	Causes:	Misadjusted Controls		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	*Comments:*	Deficiency: some are distribution area issues. The system is 26 years old. May need to be rebalanced after new boilers installed.		
	Ventilation	D3060		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	New DDC system in 2022. System should be checked for IAQ.		
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		90.00% Good
	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Multiple lighting fixtures at front of building do not work		
Communications	Data Communications	D6010		100.00% Excellent
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electronic Safety and Security	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		100.00% Excellent
Integrated Automation	Integrated Automation Facility Controls	D8010		100.00% Excellent
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	New DDC system 2022		
Equipment	Vehicle and Pedestrian Equipment	E1010		90.00% Good
	Commercial Equipment	E1030		62.00% Fair
	Deficiencies:	Other		
	Causes:	Age Deterioration, Use Deterioration		
	Comments:	03/07/17 Dishwasher and Ice Machines need frequent repair and parts replacement		
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Deficiencies:	Surface Deterioration		
	Causes:	Physical Damage		
	Comments:	Noticed a number of fixtures being replaced in 2022.		
	Movable Furnishings	E2050		90.00% Good
	Deficiencies:	Surface Deterioration		
	Causes:	Physical Damage		
	Comments:	Noticed a number of fixtures being replaced in 2022.		

Sarah J. Anderson Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	8/8/2005
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District
COMMENTS	added six classrooms in 2014 no renovation to the existing building

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	19	94.69	District	Not Reported
2023-2024	18	94.69	District	4/9/2024
2022-2023	17	94.69	District	3/14/2023
2021-2022	16	94.23	District	2/8/2022
2020-2021	15	96.19	Consultant	2/9/2021
2019-2020	14	96.25	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2004	001	13,116	13,116	13,116		
2004	010	12,266	12,266	12,266		
2004	005	10,739	10,739	10,739		
2004	006	10,711	10,711	10,711		
2004	009	8,684	8,684	8,684		
2004	003	5,431	5,431	5,431		
2004	007	4,512	4,512	4,512		
2004	002	3,967	3,967	3,967		

2004	004	1,294	1,294	1,294
2014	011	4,519	4,519	4,519
	Building Totals	**75,239**	**75,239**	**75,239**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: Lower North Co-op, staff room and other co-ops Deficiency: Noted floor tiles that are coming up, breaking loose. Might attribute to problems with concrete under. 2021 Back hallway most tiles are cracked.		
	Pits and Bases	A4040		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent
Superstructure	Floor Construction	B1010		100.00% Excellent
	Roof Construction	B1020		90.00% Good
	Stairs	B1080		100.00% Excellent
Exterior Vertical Enclosures	Exterior Walls	B2010		100.00% Excellent
	Exterior Windows	B2020		100.00% Excellent
	Exterior Doors and Grilles	B2050		100.00% Excellent
	Exterior Louvers and Vents	B2070		100.00% Excellent
Exterior Horizontal Enclosures	Roofing	B3010		90.00% Good
	Comments:	Corrective action 2022, patched various holes/ breaks		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	Roof Appurtenances	B3020		100.00% Excellent
	Horizontal Openings	B3060		100.00% Excellent
	Overhead Exterior Enclosures	B3080		100.00% Excellent
Interior Construction	Interior Partitions	C1010		100.00% Excellent
	Comments:	Location: Media Center, front hall by family resource center Deficiency: Water leaks through, signs of mold, hole in ceiling Corrective Actions: Repaired, revised drain		
	Interior Windows	C1020		100.00% Excellent
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		100.00% Excellent
	Raised Floor Construction	C1060		100.00% Excellent
	Suspended Ceiling Construction	C1070		100.00% Excellent
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Interior Fabrications	C2020		100.00% Excellent
	Flooring	C2030		90.00% Good
	Comments:	Location: North Co-Op, Staff room Deficiency: Loose or cracked floor tiles		
	Stair Finishes	C2040		90.00% Good
	Ceiling Finishes	C2050		90.00% Good
	Comments:			
Conveying	Vertical Conveying Systems	D1010		90.00% Good
	Comments:			
Plumbing	Domestic Water Distribution	D2010		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Plumbing	*Deficiencies:*	Water Leaking		
	Causes:	Excessive Wear		
	Comments:	Water heater 1 leaking, standing water and rust on floor/ Water softener tank was leaking and was bypassed. Replaced summer 2023		
	Sanitary Drainage	D2020		90.00% Good
	Deficiencies:	Clogged Drains		
	Causes:	Other		
	Comments:	Design causes periodic blockages in staff and girls gang restroom. Creates quite a mess.		
	Building Support Plumbing Systems	D2030		100.00% Excellent
HVAC	Facility Fuel Systems	D3010		100.00% Excellent
	Heating Systems	D3020		90.00% Good
	Comments:	Installation of 1 new boiler 2021. need other one replaced.		
	Cooling Systems	D3030		90.00% Good
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		100.00% Excellent
	Electrical Services and Distribution	D5020		100.00% Excellent
	General Purpose Electrical Power	D5030		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electrical	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		100.00% Excellent
	Audio-Video Communications	D6030		100.00% Excellent
	Distributed Communications and Monitoring	D6060		90.00% Good
	Deficiencies:	Weak or Intermittent Com		
	Causes:	Other		
	Comments:	Bells cannot be heard outside. Clocks failing regularly.		
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Electronic Surveillance	D7030		100.00% Excellent
	Detection and Alarm	D7050		100.00% Excellent
Integrated Automation	Integrated Automation Facility Controls	D8010		100.00% Excellent
Equipment	Commercial Equipment	E1030		90.00% Good
	Deficiencies:	Other		
	Causes:	Age Deterioration		
	Comments:	Kitchen walk in refrigerators collect condensation causing mold on walls.		
	Institutional Equipment	E1040		100.00% Excellent
	Entertainment and Recreational Equipment	E1070		100.00% Excellent
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Deficiencies:	Surface Deterioration		
	Causes:	Physical Damage		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Furnishings	*Comments:*	Missing chunks of laminate.		
	Movable Furnishings	E2050		90.00% Good
	Deficiencies:	Other		
	Causes:	Deterioration		
	Comments:	Cafeteria tables and chairs, student desks		

Washington Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	11/8/2004
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	20	88.22	District	Not Reported
2023-2024	19	88.22	District	4/9/2024
2022-2023	18	88.22	Consultant	3/14/2023
2021-2022	17	88.41	District	2/8/2022
2020-2021	16	88.41	District	2/9/2021
2019-2020	15	88.41	District	2/18/2020

The next certified BCA is due: 2028

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2003	001	11,926	11,926	11,926		
2003	004	11,151	11,151	11,151		
2003	007	8,298	8,298	8,298		
2003	008	6,954	6,954	6,954		
2003	002	5,825	5,825	5,825		
2003	003	4,198	4,198	4,198		
2003	006	2,521	2,521	2,521		
	Building Totals	**50,873**	**50,873**	**50,873**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Floor Construction	B1010		100.00% Excellent
	Roof Construction	B1020		90.00% Good
	Deficiencies:	Leaking		
	Comments:	Corrective Actions: Contracted repair summer 2015		
	Stairs	B1080		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		100.00% Excellent
	Deficiencies:	Leaking		
	Causes:	Surface Weathering		
	Comments:	Location: Washington, over media center, 2013/14 changed to all over building Deficiency: Membrane roof materal wearing badly. Had manufacturer out to make warranty repair. Corrective Actions: Made many in house repairs, warranty work. Contracted repairs and partial recovering, summer 2015		
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Deficiencies:	Acoustical Transference		
	Causes:	Other		
	Comments:	03/07/17 Interior walls that are perpendicular to fluted metal decking are not acoustically sealed at the top; acoustics very poor		
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
Interior Finishes	Wall Finishes	C2010		62.00% Fair
	Deficiencies:	Efflorescence and Staining, Surface Appearance		
	Causes:	Moisture, Surface Damage		
	Comments:	GWB has normal wear and tear and needs paint touchup; Tack Panels need cleaning and/or replacement; Some efflorescence in gym and entry hall on brick; some grout at tile stained.		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		62.00% Fair
	Deficiencies:	Other		
	Causes:	Deterioration		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Comments:*	Location: All Hallways, laminate flooring coming apart at the seems all over the school. Deficiency: Fraying at the carpet seams though out the hallways 03/07/17: VCT cracking and seams separating, cracking at flooring transitions; bathroom tile worn and staining at wet locations; wood strip flooring needs refinishing at stage		
	Stair Finishes	C2040		62.00% Fair
	Deficiencies:	Stains, Discoloration		
	Causes:	Deterioration		
	Comments:	Rubber treads and risers discoloring and joints starting to separate; all metal needs repainted		
	Ceiling Finishes	C2050		90.00% Good
	Deficiencies:	Surface Appearance		
	Causes:	Moisture, Surface Damage		
	Comments:	03/07/17 some tiles have water staining due to prior roof leaks; tiles at filter locations are damaged from frequent access		
Conveying	Vertical Conveying Systems	D1010		90.00% Good
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Sanitary Drainage	D2020		90.00% Good
	Building Support Plumbing Systems	D2030		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Deficiencies:	Other, System Inefficient		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	*Causes:*	Equipment Obsolescence, Other		
	Comments:	Deficiency: one of two boilers is needing replacement. burinign through the refractory. Lack of controlls to the second boiler. Taxing the one replaced clearfire boiler.		
	Cooling Systems	D3030		90.00% Good
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
	Comments:	Deficiency: Positive pressure - over pressurizing cause due to a lack of control. Corrective Actions: Corrections made summer 2015		
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electronic Safety and Security	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		62.00% Fair
	Deficiencies:	System Not working to Capacity		
	Causes:	Other		
	Comments:	03/07/17 HVAC System needs recommissioning		
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good

Lake Shore Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Single Story
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	3/13/2000
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	25	93.83	District	Not Reported
2023-2024	24	93.83	District	4/9/2024
2022-2023	23	93.83	District	3/14/2023
2021-2022	22	92.10	District	2/8/2022
2020-2021	21	92.07	Consultant	2/9/2021
2019-2020	20	92.07	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1999	005	17,865	17,865	17,865		
1999	008	16,600	16,600	16,600		
1999	001	16,590	16,590	16,590		
1999	006	4,243	4,243	4,243		
1999	004	4,163	4,163	4,163		
1999	007	3,829	3,829	3,829		
1999	003	3,271	3,271	3,271		
1999	002	2,617	2,617	2,617		
	Building Totals	**69,178**	**69,178**	**69,178**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent
Superstructure	Roof Construction	B1020		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Deficiencies:	Efflorescence and Staining, Other		
	Causes:	Moisture Intrusion, Moisture Penetration, Other		
	Comments:	Location: Gym Walls by garbage pit, Deficiency: efflorescence on walls, Brick needs to be water sealed. Gym, cafe'. Stage, exit in cafeteria		
	Exterior Windows	B2020		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Gas loss, hazy		
	Exterior Doors and Grilles	B2050		100.00% Excellent
	Exterior Louvers and Vents	B2070		100.00% Excellent
Exterior Horizontal Enclosures	Roofing	B3010		90.00% Good
	Deficiencies:	Leaking, Other		
	Causes:	Other, Surface Weathering		
	Comments:	Location: Skylight when wind blows to south. new seals have been recommended. In House repairs done summer 2022 to drain areas on all sections		
	Roof Appurtenances	B3020		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	*Deficiencies:*	Other		
	Causes:	Other, Surface Weathering		
	Comments:	will need paint in next couple of years		
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		100.00% Excellent
Interior Construction	Interior Partitions	C1010		90.00% Good
	Deficiencies:	Damaged or Missing Materials		
	Causes:	Other		
	Comments:	Bottom sound dampers do not all work.- Gym		
	Interior Windows	C1020		90.00% Good
	Comments:	Seal lost in some windows		
	Interior Doors	C1030		90.00% Good
	Deficiencies:	Deficient Hardware/Operating Parts		
	Causes:	Other		
	Comments:	Can't open or close windows, blinds get in the way, bad design?		
	Interior Grilles and Gates	C1040		100.00% Excellent
	Raised Floor Construction	C1060		100.00% Excellent
	Suspended Ceiling Construction	C1070		100.00% Excellent
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Deficiencies:	Efflorescence and Staining, Other		
	Causes:	Moisture, Other		
	Comments:	Through the brick in the gym, cafe', stage. Bricks need water seal.		
	Interior Fabrications	C2020		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Comments:*	Location:		
	Flooring	C2030		90.00% Good
	Deficiencies:	Irregular Surface		
	Causes:	Faulty Installation, Other		
	Comments:	Main Entry, broken ceramic tiles from earthquake, 200 wing, 300 wing vinyl tile. Concrete not floated well, rough, wavy, chunks under tile.		
	Ceiling Finishes	C2050		100.00% Excellent
Plumbing	Domestic Water Distribution	D2010		100.00% Excellent
	Deficiencies:	Discolored Fixtures		
	Causes:	Other		
	Comments:	Location: Copper plumbing lines near dishwasher Deficiency: Corrosion, blue,		
	Sanitary Drainage	D2020		100.00% Excellent
	Building Support Plumbing Systems	D2030		100.00% Excellent
HVAC	Facility Fuel Systems	D3010		100.00% Excellent
	Heating Systems	D3020		90.00% Good
	Comments:	Repairs were made improving,		
	Cooling Systems	D3030		90.00% Good
	Comments:	Chiller was rebuilt 2022		
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Deficiencies:	Inoperable Devices		
	Causes:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	*Comments:*	Deficiency: multiple failures on actuators. Parts difficult to come by. Controls need upgraded		
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Electrical Services and Distribution	D5020		100.00% Excellent
	General Purpose Electrical Power	D5030		100.00% Excellent
	Lighting	D5040		100.00% Excellent
Communications	Data Communications	D6010		100.00% Excellent
	Comments:			
	Voice Communications	D6020		90.00% Good
	Comments:			
	Audio-Video Communications	D6030		90.00% Good
	Comments:			
	Distributed Communications and Monitoring	D6060		100.00% Excellent
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Comments:			
	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		100.00% Excellent
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
	Comments:			
Equipment	Commercial Equipment	E1030		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Equipment	Institutional Equipment	E1040		100.00% Excellent
	Other Equipment	E1090		90.00% Good
	Comments:			
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Deficiencies:	Will Not Operate		
	Causes:	Deterioration, Operation Abuse or Vibrations, Other		
	Comments:	Location: Blinds,		
	Movable Furnishings	E2050		90.00% Good

Hazel Dell Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	3/24/2004
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	21	87.37	District	Not Reported
2023-2024	20	87.37	District	4/9/2024
2022-2023	19	88.52	Consultant	3/14/2023
2021-2022	18	88.92	District	2/8/2022
2020-2021	17	89.52	District	2/9/2021
2019-2020	16	89.52	District	2/18/2020

The next certified BCA is due: 2028

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2003	001	12,305	12,305	12,305		
2003	002	7,818	7,818	7,818		
2003	004	7,744	7,744	7,744		
2003	010	7,240	7,240	7,240		
2003	008	6,885	6,885	6,885		
2003	009	5,122	5,122	5,122		
2003	003	4,792	4,792	4,792		
2003	005	2,938	2,938	2,938		
2003	007	1,673	1,673	1,673		

2003	006	1,445	1,445	1,445
	Building Totals	**57,962**	**57,962**	**57,962**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Pits and Bases	A4040		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Floor Construction	B1010		100.00% Excellent
	Roof Construction	B1020		90.00% Good
	Stairs	B1080		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Age of masonry shows some signs of minor cracks and weathering.		
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		62.00% Fair
	Deficiencies:	Faulty Material, Leaking		
	Causes:	Cracks, Tears, Holes, and Breaks, Protective Coating, Surface Weathering		
	Comments:	Cleaned and recoated in 2018 Coating has failed in multiple areas causing leaks through original membrane		
	Roof Appurtenances	B3020		62.00% Fair

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	*Deficiencies:*	Faulty Material, Leaking		
	Causes:	Cracks, Tears, Holes, and Breaks, Protective Coating, Surface Weathering		
	Comments:	Roof coating installed in 2018 has failed in areas causing multiple leaks		
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Comments:	03/07/17 Operable wall between Commons and Gym does not lock in place, Corrected in 2021		
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Deficiencies:	Frame/Molding Warped		
	Causes:	Frame/Molding Condition		
	Comments:	Hard to push		
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
	Comments:			
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Deficiencies:	Cracking, Peeling, Flaking, Surface Appearance		
	Comments:	Deficiency: Some chipping		
	Interior Fabrications	C2020		90.00% Good
	Comments:	Corrected 2018		
	Flooring	C2030		62.00% Fair
	Deficiencies:	Broken or Loose Tiles		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Causes:*	Deterioration		
	Comments:	Location: First Floor Deficiency: Cracks, Tiles separating. Cracks in Cafeteria, kinder co-op. 2021 No change		
	Stair Finishes	C2040		90.00% Good
	Comments:			
	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		90.00% Good
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Sanitary Drainage	D2020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Defective Traps		
	Comments:	Deficiency: Trap primers do not keep adequate water levels to keep odors out. Corrective Actions: In housework order to repair/ replace traps. Done 2013 summer. 2021 Still a problem, Contacting Supervisor to discuss.		
	Building Support Plumbing Systems	D2030		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Toilets require multiple flushes to function		
HVAC	Facility Fuel Systems	D3010		100.00% Excellent
	Heating Systems	D3020		90.00% Good
	Cooling Systems	D3030		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	Facility HVAC Distribution Systems	D3050		90.00% Good
	Deficiencies:	Inoperable Devices, Insufficient Air Flow, Uneven Zone Coverage		
	Causes:	Equipment Obsolescence		
	Comments:	Deficiency: controls not working properly. Parts very difficult to find/procure. 2021 This has been worked on.		
	Ventilation	D3060		90.00% Good
	Deficiencies:	Stuffy Areas		
	Causes:	Other		
	Comments:	Location: Upper floor Deficiency: Odor coming through HVAC system Corrective Actions: Several work orders. unable to adjust the system to provide corrective action 03/07/17 Support staff indicates that odor source was identified		
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		90.00% Good
	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		100.00% Excellent
	Voice Communications	D6020		100.00% Excellent
	Audio-Video Communications	D6030		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Communications	Distributed Communications and Monitoring	D6060		100.00% Excellent
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		90.00% Good
	Comments:	New cameras added 2018.		
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	03/07/17 Controls for HVAC are proprietary and don't work at dampers, taxes the boiler system		
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good

Salmon Creek Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	6/13/2005
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	19	91.55	District	Not Reported
2023-2024	18	92.79	District	4/9/2024
2022-2023	17	92.79	District	3/14/2023
2021-2022	16	94.68	District	2/8/2022
2020-2021	15	94.68	Consultant	2/9/2021
2019-2020	14	94.68	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2004	005	12,523	12,523	12,523		
2004	008	10,506	10,506	10,506		
2004	002	10,408	10,408	10,408		
2004	001	8,890	8,890	8,890		
2004	007	8,087	8,087	8,087		
2004	004	8,028	8,028	8,028		
2004	003	3,939	3,939	3,939		
	Building Totals	**62,381**	**62,381**	**62,381**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		100.00% Excellent
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: Boys bathroom, main level, north co-op Deficiency: Floors slope away from drain		
	Pits and Bases	A4040		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent
	Causes:	Other		
	Comments:	Location: Boys bathroom, N. Co-op Deficiency: Floor slopes wrong Water on floor does not travel to drain. Additional: Causes problem when cleaning and toilets over flow		
Superstructure	Floor Construction	B1010		100.00% Excellent
	Roof Construction	B1020		100.00% Excellent
	Stairs	B1080		100.00% Excellent
Exterior Vertical Enclosures	Exterior Walls	B2010		100.00% Excellent
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		30.00% Poor
	Deficiencies:	Faulty Material, Leaking		
	Causes:	Cracks, Tears, Holes, and Breaks, Protective Coating, Standing Water, Surface Weathering		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	*Comments:*	Reoccurring roof leaks. More areas including main office, nurses room, rm 213, stairwells, etc.		
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Deficiencies:	Deficient Hardware/Operating Parts		
	Comments:	Location: All restrooms Deficiency: Stall door hardware not working correctly, hard to lock		
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
	Comments:	Corrective Actions: all damaged tiles replaced		
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Deficiencies:	Cracking, Peeling, Flaking, Surface Appearance		
	Causes:	Other		
	Comments:	Location: Most of the building, mentioned 103 and 111 Deficiency: Interior paint is wearing thin		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		90.00% Good
	Stair Finishes	C2040		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Inspection good till 10-2020		
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Comments:	Location: Kitchen Deficiency: Shut off valve broken, pressue valve coloration Corrective Actions: Work order in, Corrected		
	Sanitary Drainage	D2020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Floor drains in boy's restroom by Room 106 are set higher than the floor. Water doesn't drain there. When restroom floods, it is a real mess. noted 2022		
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Cooling Systems	D3030		90.00% Good
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electrical	Electrical Services and Distribution	D5020		100.00% Excellent
	General Purpose Electrical Power	D5030		100.00% Excellent
	Lighting	D5040		100.00% Excellent
Communications	Data Communications	D6010		100.00% Excellent
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Deficiencies:	Electronic Locks Not Functioning		
	Causes:	Other		
	Comments:	Location: card reader on East Entry Deficiency: Showing minor damage but still funtional.		
	Electronic Surveillance	D7030		90.00% Good
	Comments:	Location: Kitchen SW wall Deficiency: Loose mounting. Used to climb onto roof		
	Detection and Alarm	D7050		100.00% Excellent
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Furnishings	Fixed Furnishings	E2010		100.00% Excellent
	Movable Furnishings	E2050		100.00% Excellent

Minnehaha Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Single Story
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	2/28/2000
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	25	84.98	District	Not Reported
2023-2024	24	84.98	District	4/9/2024
2022-2023	23	84.98	District	3/14/2023
2021-2022	22	90.71	District	2/8/2022
2020-2021	21	87.38	Consultant	2/9/2021
2019-2020	20	87.38	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1999	001	15,607	15,607	15,607		
1999	008	11,401	11,401	11,401		
1999	005	10,458	10,458	10,458		
1999	007	10,289	10,289	10,289		
1999	006	6,894	6,894	6,894		
1999	003	5,262	5,262	5,262		
1999	009-Covered Play	2,456	2,456	1,228		
1999	004	2,413	2,413	2,413		
1999	002	2,144	2,144	2,144		

Building Totals	**66,924**	**66,924**	**65,696**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		100.00% Excellent
Superstructure	Roof Construction	B1020		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		62.00% Fair
	Deficiencies:	Leaking		
	Causes:	Cracks, Tears, Holes, and Breaks, Other		
	Comments:	Ongoing leaks in kitchen, cafeteria, music hall storage, gym corner. Some areas not draining due to no slope.		
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	Wall Finishes	C2010		62.00% Fair
	Deficiencies:	Other, Surface Appearance		
	Causes:	Other, Surface Damage		
	Comments:	Age of school		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		62.00% Fair
	Deficiencies:	Stains, Discoloration		
	Causes:	Other		
	Comments:	Many carpets did not get stains out. Marmoleum damaged due to Covid spacing stickers.		
	Ceiling Finishes	C2050		90.00% Good
Plumbing	Domestic Water Distribution	D2010		100.00% Excellent
	Comments:	New HW Heater!		
	Sanitary Drainage	D2020		90.00% Good
HVAC	Facility Fuel Systems	D3010		62.00% Fair
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	age of system		
	Heating Systems	D3020		62.00% Fair
	Deficiencies:	Other		
	Causes:	Equipment Obsolescence, Other		
	Comments:	Age of system but working		
	Cooling Systems	D3030		90.00% Good
	Comments:	New Chiller added 2018		
	Facility HVAC Distribution Systems	D3050		62.00% Fair

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	*Deficiencies:*	Other		
	Causes:	Other		
	Comments:	Building Operator feels balancing is needed. Noisy contactor issue has been resolved. Repairs were made summer 2021 on the North Wing Unit 30 and unit 40 and all systems are working at the time of assessment.		
	Ventilation	D3060		90.00% Good
	Comments:	2021 saw extensive work on HVAC systems, Exhaust Fans including changing fan modes to on/ slow when system is scheduled on. This resolved complaints of noise as fans kicked on during the school day and provided constant ventilation. Regular maintenance has been performed including belts, filters and lubrication.		
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		100.00% Excellent
	Comments:	Phone system replaced in 2022.		
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Electronic Surveillance	D7030		100.00% Excellent
	Comments:	Summer 2021 saw major upgrade to digital from analog cameras. 2022 new cameras installer outside, Blind sports now covered.		
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Deficiencies:	Other		
	Causes:	Age Deterioration, Other		
	Comments:	age of equipment, unspecified.		
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		62.00% Fair
	Comments:	Many tables no longer adjust		

Fruit Valley Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Single Story
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	6/9/2003
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District
COMMENTS	no major renovation occurred in 2005. Gym and Covered Play area constructed in 2005. Portion of building used for contracted daycare service.

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	21	87.56	District	Not Reported
2023-2024	20	87.56	District	4/9/2024
2022-2023	19	87.56	Consultant	3/14/2023
2021-2022	18	85.22	District	2/8/2022
2020-2021	17	85.22	District	2/9/2021
2019-2020	16	85.22	District	2/18/2020

The next certified BCA is due: 2028

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2002	011	8,555	8,555	8,555		
2002	006	4,126	4,126	4,126		
2002	010	3,452	3,452	3,452		
2002	003	3,116	3,116	3,116		
2002	009	1,876	1,876	938		
2002	002	1,680	1,680	1,680		
2002	005	1,609	1,609	1,609		
2002	004	1,455	1,455	1,455		
2002	001	1,254	1,254	627		

2005	008	8,747	8,747	8,747
2005	007	4,145	4,145	4,145
	Building Totals	**40,015**	**40,015**	**38,450**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Roof Construction	B1020		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Exterior Windows	B2020		90.00% Good
	Deficiencies:	Other		
	Causes:	Material Condition		
	Comments:	Noticed several clerestory windows had broken seals. Will need to be replaced.		
	Exterior Doors and Grilles	B2050		90.00% Good
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		100.00% Excellent
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Roofing being replaced summer 2022. This includes all areas.		
	Roof Appurtenances	B3020		62.00% Fair
	Deficiencies:	Fastening Failure, Gutters/Downspouts Not Draining		
	Causes:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	*Comments:*	03/07/17 Fastening failure at downspouts; gutter at front of builidng overfills with hard rain and water runs down face of building		
	Horizontal Openings	B3060		90.00% Good
	Overhead Exterior Enclosures	B3080		90.00% Good
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		62.00% Fair
	Deficiencies:	Irregular Surface		
	Causes:	Deterioration, Settlement		
	Comments:	Location: Media center, office & cafeteria Deficiency: Gaps and cracks 03/07/17 VCT cracking and splitting at seams and over slab expansion joints This is not stopping and has gotten worse. There is settlement in this area. Tiles are starting to chip along edge of gap. 2022		
	Ceiling Finishes	C2050		90.00% Good
	Deficiencies:	Surface Appearance		
	Causes:	Surface Damage		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Comments:*	water damage from leaking roof has stained some tiles. With new roof being installed 2022, these tiles are scheduled to be replaced with new.		
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Deficiencies:	Water Leaking		
	Causes:	Defective Valves		
	Comments:	Location: Hot water tank Deficiency: Valve leaks Corrective Actions: In house repairs requested		
	Sanitary Drainage	D2020		90.00% Good
	Building Support Plumbing Systems	D2030		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Cooling Systems	D3030		62.00% Fair
	Deficiencies:	Inoperable Devices, Insufficient Cooling		
	Causes:	Equipment Obsolescence		
	Comments:	HVAC tech reported that the chiller needs work.		
	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Fire Protection	*Comments:*	03/07/17 Dry system found to have pinhole leaks in some areas and rusted the fittings; all will need replaced eventually		
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Deficiencies:	Surface Deterioration, Unsightly		
	Causes:	Deterioration, Looseness of Fasteners, Surface Water		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Furnishings	*Comments:*	03/07/17 Plastic Laminate deterioration/delamination in restrooms and general casework along edge, backsplash, and corners		
	Movable Furnishings	E2050		90.00% Good
	Deficiencies:	Surface Deterioration, Unsightly		
	Causes:	Deterioration, Looseness of Fasteners, Physical Damage		
	Comments:	03/07/17 Plastic laminate delamination at face and tops of moveable furnishings		

Benjamin Franklin Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Single Story
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	6/28/2004
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	20	89.57	District	Not Reported
2023-2024	19	89.98	District	4/9/2024
2022-2023	18	89.98	Consultant	3/14/2023
2021-2022	17	89.99	District	2/8/2022
2020-2021	16	89.93	District	2/9/2021
2019-2020	15	87.57	District	2/18/2020

The next certified BCA is due: 2028

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2003	006	11,857	11,857	11,857		
2003	005	8,580	8,580	8,580		
2003	001	7,747	7,747	7,747		
2003	002	5,094	5,094	5,094		
2003	004	3,115	3,115	3,115		
2003	003	967	967	967		
	Building Totals	**37,360**	**37,360**	**37,360**		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Deficiencies:	Minor Cracking		
	Causes:	Other		
	Comments:	Some cracking per building operator		
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Roof Construction	B1020		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Deficiencies:	Efflorescence and Staining		
	Causes:	Moisture Intrusion		
	Comments:	Location: CMU brick in chiller area and outside storage room Deficiency: Some efflorescence, Recaulking done 2021		
	Exterior Windows	B2020		90.00% Good
	Exterior Doors and Grilles	B2050		90.00% Good
	Deficiencies:	Other		
	Causes:	Caulking/Weather Stripping		
	Comments:	Location: South East Corner of Gym Deficiency: Gap at corner of sheet metal siding Additional: Efflorescence on walls by chiller		
	Exterior Louvers and Vents	B2070		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		100.00% Excellent
	Comments:	Location: New Roof 8/2020		
	Roof Appurtenances	B3020		100.00% Excellent
	Horizontal Openings	B3060		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	Overhead Exterior Enclosures	B3080		90.00% Good
	Deficiencies:	Other		
	Causes:	Surface Damage		
	Comments:	Beams with natural wood exposure are showing signs of weathering and will need to be treated within next couple of years.		
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Comments:	Location: Deficiency: Window Frames have been reattached.		
	Interior Doors	C1030		90.00% Good
	Deficiencies:	Other		
	Causes:	Material Condition		
	Comments:	Location: Classroom doors and window mouldings Deficiency: Need to be fastened more securly. A good amount of them are starting to come loose		
	Interior Grilles and Gates	C1040		90.00% Good
	Raised Floor Construction	C1060		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: Work room tiles get wet from a drain problem in boiler room Corrective Actions: Replace as needed		
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Deficiencies:	Cracking, Peeling, Flaking		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Interior Finishes	*Causes:*	Settlement		
	Comments:	Location: Throughout Building Deficiency: Cracks at joints & corners Corrective Actions: cosmetic touch ups		
	Interior Fabrications	C2020		90.00% Good
	Deficiencies:	Surface Appearance		
	Causes:	Other		
	Comments:	Location: Class rooms Deficiency: chairs rub on walls		
	Flooring	C2030		62.00% Fair
	Deficiencies:	Broken or Loose Tiles, Holes, Tears		
	Causes:	Deterioration, Settlement		
	Comments:	Location: 100 wing. 200 wing, stage steps and music room ramp Deficiency: 8 VCT chipped or cracked, Ramp sheet vinal hole, 2" 03/07/17 VCT splitting and cracking at seams and concrete expansion joints at numerous locations		
	Ceiling Finishes	C2050		90.00% Good
	Comments:	Location: Outside storage room Deficiency: Some sheetrock moisture damage		
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Sanitary Drainage	D2020		90.00% Good
	Building Support Plumbing Systems	D2030		90.00% Good
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Cooling Systems	D3030		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	Facility HVAC Distribution Systems	D3050		90.00% Good
	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		100.00% Excellent
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		90.00% Good
	Deficiencies:	Other		
	Causes:	Other		
	Comments:	Location: generator Deficiency: Do not have maintenance procedures for installed generator		
	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		100.00% Excellent
	Comments:	Location: Hub room Deficiency: No AC, vented only		
	Voice Communications	D6020		100.00% Excellent
	Audio-Video Communications	D6030		100.00% Excellent
	Comments:	Now Wireless.		
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Electronic Surveillance	D7030		100.00% Excellent
	Detection and Alarm	D7050		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Deficiencies:	Will Not Operate		
	Causes:	Other		
	Comments:	Location: Window blinds in most rooms Deficiency: Showing damage, some excessive wear. Corrective Actions: Work orders are being placed for contracted repairs.		
	Movable Furnishings	E2050		90.00% Good
	Deficiencies:	Surface Deterioration, Unsightly		
	Causes:	Physical Damage		
	Comments:	Location: Not specified Deficiency: Some folding walls have fabric tears Corrective Actions: Work order for in house repair		

Dwight D. Eisenhower Elementary School - Main Building

Building Details

PROFILE TYPE	Elementary School - Multi-Story
NUMBER OF FLOORS	2
BOARD ACCEPTANCE DATE	12/10/2007
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District
COMMENTS	Note by Bill Coon. There is a discrepency on the SF reported for this SCAP new construction. In 2005 the A/E certified 68,150sf but the district shows 69,114sf and does not report any new additions since 2006. I am asking the district to clarify.

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	17	93.62	District	Not Reported
2023-2024	16	93.62	District	4/9/2024
2022-2023	15	93.62	District	3/14/2023
2021-2022	14	94.24	District	2/8/2022
2020-2021	13	94.24	Consultant	2/9/2021
2019-2020	12	94.44	District	2/18/2020

The next certified BCA is due: 2026

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2006	004	14,025	14,025	14,025	9/1/2006	12/10/2007
2006	005	11,614	11,614	11,614	9/1/2006	12/10/2007
2006	006	9,837	9,837	9,837	9/1/2006	12/10/2007
2006	003	8,661	8,661	8,661	9/1/2006	12/10/2007
2006	007	7,614	7,614	7,614	9/1/2006	12/10/2007
2006	002	6,908	6,908	6,908	9/1/2006	12/10/2007
2006	008	6,473	6,473	6,473	9/1/2006	12/10/2007
2006	001	2,782	2,782	2,782	9/1/2006	12/10/2007

Building Totals	**67,914**	**67,914**	**67,914**

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
	Deficiencies:	Minor Cracking		
	Causes:	Other		
	Comments:	Deficiency: Floor slab cracked in commons settlement cracks		
	Pits and Bases	A4040		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Floor Construction	B1010		90.00% Good
	Roof Construction	B1020		90.00% Good
	Stairs	B1080		90.00% Good
Exterior Vertical Enclosures	Exterior Walls	B2010		100.00% Excellent
	Exterior Windows	B2020		100.00% Excellent
	Deficiencies:	Other		
	Causes:	Caulking/Weather Stripping, Other		
	Comments:	Window Seals and caulking are shrinking and causing some leaks.		
	Exterior Doors and Grilles	B2050		90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010		100.00% Excellent
	Roof Appurtenances	B3020		90.00% Good
	Causes:	Surface Weathering		
	Comments:	Deficiency: Paint failure on sheetmetal cover on two small rooftop consensing units. Replace or restore finish		
	Horizontal Openings	B3060		90.00% Good

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Horizontal Enclosures	Overhead Exterior Enclosures	B3080		100.00% Excellent
Interior Construction	Interior Partitions	C1010		90.00% Good
	Interior Windows	C1020		90.00% Good
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
	Suspended Ceiling Construction	C1070		90.00% Good
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Deficiencies:	Efflorescence and Staining		
	Causes:	Other, Surface Damage		
	Comments:	Deficiency: Efflorescence on masonry in commons		
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		90.00% Good
	Deficiencies:	Holes, Tears		
	Causes:	Other, Sealing		
	Comments:	Deficiency: Minor repairs need at marmoleum surface at entry door and stairway 2018Flooring coming up again by all doors and entrances		
	Stair Finishes	C2040		90.00% Good
	Ceiling Finishes	C2050		90.00% Good
Conveying	Vertical Conveying Systems	D1010		100.00% Excellent
Plumbing	Domestic Water Distribution	D2010		90.00% Good
	Sanitary Drainage	D2020		100.00% Excellent
	Building Support Plumbing Systems	D2030		100.00% Excellent

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	Facility Fuel Systems	D3010		100.00% Excellent
	Heating Systems	D3020		100.00% Excellent
	Cooling Systems	D3030		100.00% Excellent
	Facility HVAC Distribution Systems	D3050		100.00% Excellent
	Ventilation	D3060		100.00% Excellent
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		100.00% Excellent
Electrical	Facility Power Generation	D5010		100.00% Excellent
	Electrical Services and Distribution	D5020		100.00% Excellent
	General Purpose Electrical Power	D5030		100.00% Excellent
	Lighting	D5040		90.00% Good
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		100.00% Excellent
	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		100.00% Excellent
Equipment	Commercial Equipment	E1030		90.00% Good
	Quantity:	1.00 Lot		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Equipment	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		90.00% Good
	Other Equipment	E1090		90.00% Good
Furnishings	Fixed Furnishings	E2010		100.00% Excellent
	Movable Furnishings	E2050		100.00% Excellent