

Date: 09/04/2026 3:39:42 PM	Pages: 5	Filename: C:\Users\HP\Desktop\1002.nc
--------------------------------	-------------	--

%
 O1001
 G0 G18 G21 G40 G54 G80 G99 M110
 M24

 N1 (FACE2)
 G0 G28 G53 B0. (SUB SPINDLE RETURN)
 G28 U0. V0.
 G28 W0.
 M90
 G54
 G99 G18 M34
 G50 S1600
 T0300
 M8
 G97 S273 M3 P11
 G0 Z5.
 X35. Y0.
 G96 S30 M3 P11
 Z0.914
 X27.
 G1 X25.828 F0.05
 X23. Z-0.5
 X-1.6 F0.1
 X1.228 Z0.914
 G0 X25.828
 G1 Z0.414 F0.05
 X23. Z-1.
 X-1.6 F0.1
 X1.228 Z0.414
 G0 X35.
 Z5.
 G97 S273 M3 P11
 M9
 G28 U0. V0.
 G28 W0.
 M110
 M1

 N2 (DRILL4)
 G0 G28 G53 B0. (SUB SPINDLE RETURN)
 G28 U0. V0.
 G28 W0.
 M5 P11
 G54
 G98 G17 M35
 M90
 G0 G28 H0.
 M89
 T0202
 M8
 G97 S1600 M3 P12
 M90
 G0 C0.
 M89
 G0 Z15.
 X0. Y0.
 G80
 G0 Z5.
 G83 Z-4. R-1. F160.
 G80
 G0 Z15.
 M5 P12
 M90
 M34
 M9
 G28 U0. V0.
 G28 W0.
 M110
 M1

 N3 (PROFILE ROUGHING3)
 G0 G28 G53 B0. (SUB SPINDLE RETURN)
 G28 U0. V0.
 G28 W0.

M5 P12
 M90
 G54
 G99 G18 M34
 G50 S1600
 T0300
 M8
 G97 S222 M3 P11
 G0 Z5.
 X43. Y0.
 G96 S30 M3 P11
 Z-0.4
 X21.2
 G1 Z-131.8 F0.15
 X23.
 X25. Z-130.8
 G0 Z-0.4
 X19.4
 G1 Z-131.8
 X21.2
 X23.2 Z-130.8
 G0 Z-0.4
 X17.15
 G1 Z-14.261
 X19.4 Z-15.386
 X21.4 Z-14.386
 G0 Z-0.4
 X14.9
 G1 Z-13.8
 X16.228
 X17.15 Z-14.261
 X19.15 Z-13.261
 G0 Z-0.4
 X12.65
 G1 Z-13.8
 X14.9
 X16.9 Z-12.8
 G0 Z-0.4
 X10.4
 G1 Z-13.8
 X12.65
 X14.65 Z-12.8
 G0 Z-0.4
 X8.097
 G1 Z-1.234
 X10.4 Z-2.386
 X12.4 Z-1.386
 G0 X43.
 Z5.
 G97 S222 M3 P11

 (PROFILE FINISHING2)
 G97 S259 M3 P11
 G0 Z5.
 X43. Y0.
 G96 S35 M3 P11
 Z0.766
 X8.642
 G1 X7.531 F0.1
 Z-1.234 F0.03
 X7.805 Z-1.371 F0.07
 X10. Z-2.469
 Z-14.
 X16.063
 X19. Z-15.469
 Z-118.8
 X23. F0.1
 G0 X43.
 Z5.
 G97 S259 M3 P11
 M9
 G28 U0. V0.
 G28 W0.
 M110
 M1

N4 (SINGLE GROOVE1)**G0 G28 G53 B0. (SUB SPINDLE RETURN)**

G28 U0. V0.

G28 W0.

M90

G54

G99 G18 M34

G50 S1600

T0101

M8

G97 S185 M3 P11

G0 Z5.**X43. Y0.**

G96 S25 M3 P11

Z-14.**G1 X7. F0.05****G0 X43.****Z5.**

G97 S185 M3 P11

M9

G28 U0. V0.

G28 W0.

M110

M1

N5 (FACE3)**G0 G28 G53 B0. (SUB SPINDLE RETURN)**

G28 U0. V0.

G28 W0.

M5 P11

G54

G98 G18 M35

M90

G0 G28 H0.

M89

T1111

M8

G97 S700 M3 P12

M90

G0 C-90.

M89

G0 Z-6.**X53. Y-13.4****X33.****G1 X11.2 F84.****G17 G2 X8. Y-11.8 I0. J1.6 F80.****G1 Y-3.****Y3. F126.****G2 X11.2 Y4.6 I1.6 J0.****G0 X53.**

M5 P12

M90

M34

M9

G28 U0. V0.

G28 W0.

M110

M1

N6 (THREAD2)**G0 G28 G53 B0. (SUB SPINDLE RETURN)**

G28 U0. V0.

G28 W0.

M5 P12

M90

G54

G99 G18 M34

T1200

M8

G97 S450 M3 P11

G0 Z5.**X43. Y0.****Z5.5****X9.77****G32 Z-10.885 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X9.54****G32 Z-10.77 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X9.31****G32 Z-10.655 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X9.08****G32 Z-10.54 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X8.85****G32 Z-10.425 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X8.62****G32 Z-10.31 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X8.39****G32 Z-10.195 F1.5****X10. Z-11. F1.5****G0 X12.****Z5.5****X8.16****G32 Z-10.08 F1.5****X10. Z-11. F1.5****G0 X43.****Z5.**

M9

G28 U0. V0.

G28 W0.

M110

M1

N7 (DRILL4 2)**G0 G28 G53 B0. (SUB SPINDLE RETURN)**

G28 U0. V0.

G28 W0.

M5 P11

G54

G98 G18 M35

M90

G0 G28 H0.

M89

T0202

M8

G97 S500 M3 P12

M90

G0 C-90.

M89

G0 Z-103.5**X53. Y0.****G0 X33.****G87 X17. R-2. F30. M89****Z-66. M89****Z-28.5 M89**

G80

G0 X53.

M5 P12

M90

M9

G28 U0. V0.

G28 W0.

M110

M1

N8 (DRILL6)**G0 G28 G53 B0. (SUB SPINDLE RETURN)**

G28 U0. V0.
G28 W0.
G54
G98 G18 M35
M90
G0 G28 H0.
M89
T0909
M8
G97 S900 M3 P12
M90
G0 C-90.
M89
G0 Z-66.
X53. Y0.
G0 X33.
G87 X-30.107 R-2. Q2500 F135. M89
G80
G0 X53.
M5 P12
M90
M9
G28 U0. V0.
G28 W0.
M110
M1

N9 (DRILL7)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
G54
G98 G18 M35
M90
G0 G28 H0.
M89
T1010
M8
G97 S1275 M3 P12
M90
G0 C-90.
M89
G0 Z-28.5
X53. Y0.
G0 X33.
G87 X-28.605 R-2. Q2500 F127.5 M89
Z-103.5 Q2500 M89
G80
G0 X53.
M5 P12
M90
M9
G28 U0. V0.
G28 W0.
M110
M1

N10 (DRILL8)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
G54
G99 G18 M35
M90
G0 G28 H0.
M89
T0808
M8
M90
G0 C-90.
M89
G0 Z-66.
X53. Y0.
G0 X33.
G97 S250 M29 P12
G88 X-19. R-2. F1.5 M89
G80

G0 X53.
M5 P12
M90
M34
M9
G28 U0. V0.
G28 W0.
M110
M1

N11 (GROOVE5)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
M5 P12
M90
G54
G99 G18 M34
G50 S1600
T1313
M8
G97 S760 M3 P11
G0 Z66.
X40. Y0.
G96 S96 M3 P11
Z10.
X27.
G1 X24. F1.
X20. F0.05
X14. F0.08
X20. F1.
G0 X24.
Z7.75
G1 X20. F0.05
X14. F0.08
X16. Z8.75 F1.
G0 X24.
Z5.5
G1 X20. F0.05
X14. F0.08
X16. Z6.5 F1.
G0 X24.
Z3.25
G1 X20. F0.05
X14. F0.08
X16. Z4.25 F1.
G0 X24.
Z1.
G1 X20. F0.05
X14. F0.08
X16. Z2. F1.
G0 X24.
Z10.
G1 X14. F0.05
X8. F0.08
X14. F1.
G0 X18.
Z7.75
G1 X14. F0.05
X8. F0.08
X10. Z8.75 F1.
G0 X18.
Z5.5
G1 X14. F0.05
X8. F0.08
X10. Z6.5 F1.
G0 X18.
Z3.25
G1 X14. F0.05
X8. F0.08
X10. Z4.25 F1.
G0 X18.
Z1.
G1 X14. F0.05
X9.766 F0.08
X11.766 Z2. F1.
G0 X24.

Z10.
G1 X8. F0.05
X2. F0.08
X8. F1.
G0 X12.
Z7.75
G1 X8. F0.05
X2. F0.08
X4. Z8.75 F1.
G0 X12.
Z5.5
G1 X8. F0.05
X2. F0.08
X4. Z6.5 F1.
G0 X13.766
Z3.25
G1 X8. F0.05
X2. F0.08
X4. Z4.25 F1.
G0 X24.
Z10.
G1 X2. F0.05
X0. F0.08
X2. F1.
G0 X6.
Z7.75
G1 X2. F0.05
X0. F0.08
X2. F1.
G0 X6.
Z5.5
G1 X2. F0.05
X0. F0.08
X2. F1.
G0 X13.766
Z3.25
G1 X2. F0.05
X0. F0.08
X2. F1.
X12.594
Z2.414
X9.766 Z1. F0.05
X7.883 Z1.941 F0.08
X7.8 Z1.973
X7.704 Z1.993
X7.6 Z2.
X0.
Z10.
X2.828 Z8.586 F1.
G0 X40.
Z66.
G97 S760 M3 P11
M9
G28 U0. V0.
G28 W0.
M110
M1

N12 (FACE2 2)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
M90
G54
G99 G18 M34
G50 S1600
T0300
M8
G97 S298 M3 P11
G0 Z66.
X32. Y0.
G96 S30 M3 P11
Z2.914
X24.
G1 X22.828 F0.05
X20. Z1.5
X-1.6 F0.1

X1.228 Z2.914
G0 X22.828
G1 Z2.414 F0.05
X20. Z1.
X-1.6 F0.1
X1.228 Z2.414
G0 X32.
Z66.
G97 S298 M3 P11

(PROFILE ROUGHING3 2)
G97 S239 M3 P11
G0 Z66.
X40. Y0.
G96 S30 M3 P11
Z1.6
X17.15
G1 Z-12.261 F0.15
X19. Z-13.186
X21. Z-12.186
G0 Z1.6
X14.9
G1 Z-11.8
X16.228
X17.15 Z-12.261
X19.15 Z-11.261
G0 Z1.6
X12.65
G1 Z-11.8
X14.9
X16.9 Z-10.8
G0 Z1.6
X10.4
G1 Z-11.8
X12.65
X14.65 Z-10.8
G0 Z1.6
X8.097
G1 Z0.766
X10.4 Z-0.386
X12.4 Z0.614
G0 X40.
Z66.
G97 S239 M3 P11

(PROFILE FINISHING2 2)
G97 S279 M3 P11
G0 Z66.
X40. Y0.
G96 S35 M3 P11
Z2.766
X8.642
G1 X7.531 F0.1
Z0.766 F0.03
X10. Z-0.469 F0.07
Z-12.
X16.063
X18.997 Z-13.467
X22.997 F0.1
G0 X40.
Z66.
G97 S279 M3 P11
M9
G28 U0. V0.
G28 W0.
M110
M1

N13 (SINGLE GROOVE1 2)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
M90
G54
G99 G18 M34
G50 S1600
T0101

M8
G97 S199 M3 P11
G0 Z66.
X40. Y0.
G96 S25 M3 P11
Z-12.
G1 X7. F0.05
G0 X40.
Z66.
G97 S199 M3 P11
M9
G28 U0. V0.
G28 W0.
M110
M1

N14 (FACE3 2)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
M5 P11
G54
G98 G18 M35
M90
G0 G28 H0.
M89
T1111
M8
G97 S700 M3 P12
M90
G0 C-90.
M89
G0 Z-4.
X50. Y13.4
X30.
G1 X11.2 F84.
G17 G3 X8. Y11.8 I0. J-1.6 F80.
G1 Y3.
Y-3. F126.
G3 X11.2 Y-4.6 I1.6 J0.
G0 X50.
M5 P12
M90
M34
M9
G28 U0. V0.
G28 W0.
M110
M1

N15 (THREAD2 2)
G0 G28 G53 B0. (SUB SPINDLE RETURN)
G28 U0. V0.
G28 W0.
M5 P12
M90
G54
G99 G18 M34
T1200
M8
G97 S450 M3 P11
G0 Z66.
X40. Y0.
Z3.
X9.77
G32 Z-8.885 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X9.54
G32 Z-8.77 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X9.31
G32 Z-8.655 F1.5
X10. Z-9. F1.5

G0 X12.
Z3.
X9.08
G32 Z-8.54 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X8.85
G32 Z-8.425 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X8.62
G32 Z-8.31 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X8.39
G32 Z-8.195 F1.5
X10. Z-9. F1.5
G0 X12.
Z3.
X8.16
G32 Z-8.08 F1.5
X10. Z-9. F1.5
G0 X40.
Z66.
M5 P11
M9

M25
G28 U0. V0.
G28 W0.
G0 G28 G53 B0. (SUB SPINDLE RETURN)
M34
G54

M111
M30
%