
Cumulative sum
h
0
reset to 0
reset to 0
Time step t (10 min per step)
C_t^{abs}
Reference adjustment k
Threshold h
Alarm point