
Cumulative sum
+h
0
−h
reset to 0
reset to 0
Time step t (10 min per step)
C_t^+
C_t^-
Reference adjustment k
Threshold ±h
Alarm point