MAINTENANCE SHIFT REPORT (FIELD SCAN)

Date: 2026-03-15 Asset ID: Y52-COLD-ROLL Technician: Tech-42

Observation: Vibration alarm triggered during roll acceleration.

Alarm Code: ALM-3025 (Servo Communication Timeout / Fiber Loss)

Action Taken: Cleaned optical fiber plug F-03 on drive module A2.

Fastener check: Confirmed 45 Nm torque applied to coupling CP-FLANGE-100.

Status: RESOLVED - Returned to active production at 14:30.

QA VERIFIED