

REPORT OF THOROUGH EXAMINATION

Client and Location of thorough examination		Client representative	Certificate number	Certificate date
The Petroleum Projects & Technical Consultations Company (PETROJET) AI-alamein		Mr.:nagy abo elhassan	CERT-2026-1198	25/09/2026
Last Through examination date	Through examination date	Next examination date	Standard of inspection	Test type
N/A	24/09/2026	23/03/2027	BS ISO 5389: 2005	Visual & function test

Item information / Test results.

Inspected Item:	Air Compressor	Manufacturer:	CATERPILLAR
Model/ year of manufacturing:	C13	MAX. working rate:	10 Bar
Serial number / Chassis number:	SN.: LGK06312	Function Check:	Pass
Owner ID:	23811	NDT:	N/A
Conclusion / remarks:		Satisfactory	

Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out:				
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 6 months?	YES	✓	NO	
					Within an interval of 12 months?	YES		NO	✓
					In accordance with an examination scheme?	YES	✓	NO	
					After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: Safety relief valve seized in the closed position. Safety relief valve seized in the closed position. Safety relief valve seized in the closed position. Safety relief valve seized in the closed position. Safety relief valve seized in the closed position.

Is the above an existing or imminent danger to persons *Note-This is a reportable defect	YES	✓	NO	
--	-----	---	----	--

Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)	YES by: 24/10/2026
---	--------------------

Particulars of any repair, renewal or alteration required to remedy the defect identified above: Replace the relief valve and re-test at 1.1x working pressure. Replace the relief valve and re-test at 1.1x working pressure. Replace the relief valve and re-test at 1.1x working pressure. Replace the relief valve and re-test at 1.1x working pressure.

Particulars of any tests carried out as part of the examination: NONE

Note: Machine tagged out of service on site. Machine tagged out of service on site. Machine tagged out of service on site. Machine tagged out of service on site. Machine tagged out of service on site. Machine tagged out of service on site. Machine tagged out of service on site.

General Notes and Recommendations	- This Certificate becomes invalid if any Repair/modification is done that affects strength or stability. - Any holder of this document is advised that the information contained hereon is limited to the accessible portions of the item examined only. - Equipment has been correctly installed and fit for the purpose - This Certificate should be signed, stamped and carries unique TUV Austria certificate number
-----------------------------------	--

Name & Qualifications of person making this report	Name of person signing or authenticating this report on behalf of the author	For TUV Austria Egypt	QR Code
Anas Hegazi	 Mahmoud Nasr	Hussein Rashad	