

## OPERATIONS MANUAL PART C

6 COMMUNICATION FAILURE PROCEDURES

6.1 ENROUTE

**Issue:** 00

**Revision:** 00

**Date:** 18-FEB-2024

### 6 COMMUNICATION FAILURE PROCEDURES

In the event of a two-way communication failure, the transponder code should be set to 7600.

#### 6.1 ENROUTE

Flight crew shall apply the communication failure procedures, contained in the Route Manual / Emergency / International Civil Aviation Organization / Communications Failure.



DOCUMENT NO: RXI/OPS-FLT-M03 SECTION - PAGE 6-1



# OPERATIONS MANUAL PART C

6 COMMUNICATION FAILURE PROCEDURES

6.2 TERMINAL AREA

**Issue:** 00

**Revision:** 00

**Date:** 18-FEB-2024

#### 6.2 TERMINAL AREA

Flight crew shall apply the communication failure procedure as documented in the applicable aerodrome reference pages, or as noted on the applicable approach chart or aerodrome reference pages.



DOCUMENT NO: RXI/OPS-FLT-M03 SECTION - PAGE 6-2