
Department of Information & Communication Technology

Follow the steps for the below errors.



- 1. **Switch off the kit** first and then change the USB port -> Look for the port number in device manager -> change the COM port in flash magic.
- 2. Go to "Options" -> Advanced Options -> Mark "High Speed Communications" and change the Baud rate to **115200** (Preferrable) -> Click **OK**
- 3. SWITCH ON THE KIT AND CLICK "Start"
- 4. For the above errors you can also try switching off the kit and changing the baud rate to 7200 and then switching ON the kit.
 - Sometimes it works on 7200 & 9600 for both erasing and downloading
 - If you change settings in advanced options, then it'll affect "erasing and downloading"

If the above steps don't work, troubleshoot it by following the below steps.

- 1. Changing the **USB** cable
- 2. Changing the RS232 cable
- 3. Change the **Power supply**.

If none of the above works, only then change the KIT.