


STATE	MOTOR	STATE TIME	NEXT STATE				
NAME	OUTPUT	DURATON (ms)	LEFT	RIGHT	BOTH	NONE	
CENTER	1.1	500	RIGHT I	LEFTI	CENTER	LOST STRAIGHT	
LEFT I	10	500	RIGHTI	LEFTIL	CENTER	LOST LEFT	
LEMI	1.1	500	RIGHTI	LEFT I	CENTER	LOGT LEFT	
LOST LEFT	10	5000	RIGHTI	LEFTI	CENTER	LOST STRAIGHT	
RIGHT I	01	500	R16HT IL	LEFTI	CENTER	LOST RIGHT	
RIGHT II	11	500	RIGHTI	LEPTI	CENTER	LOST RIGHT	
LOST RIGHT	01	5000	RIGHTI	LEFTI	CENTER	LOST STRAIGHT	
LOST STRAIGHT	11	5000	RIGHTI	LEFTI	CENTER	T. LOST	
TOTALLY LOST	00	500	T. LOST	T.LOST	۳. نود ۲	۲۰ ما	



STATE	MOTOR	STATE TIME	NEXT STATE					
NAME	OUTPUT	DURATON (ms)	NONE	MIDDLE 2	RIGHTZ	RIGHT 1	LEPT 2	LEFT 1
CENTER	1.1	500	LOST STRAGHT	CENTER	LEFTI	FAR LEFT	RIGHT I	RIGHTI
LEFT I	10	500	FAR	LEFTIL	LEFTIL	FAR LEFT	RIGHT I	RIGHTI
LEFTI	1 \	500	FAR	CENTER	LEFT I	FARLEFT	RIGHT I	RIGHT I
FAR LEFT	10	5000	LOST STRAIGHT	LEFTIL	LEPTI	FAR LEFT	RIGHT I	RIGHTI
RIGHT I	01	500	FAR	RIGHTIL	LEFTI	LEFTI	RIGHT II	FAR RIGHT
RIGHT II	11	500	PAR RIGHT	CENTER	LEFTI	LEFTI	RIGHT I	FAR RIGHT
FAR RIGHT	01	5000	STRAGHT	RIGHTI	LEFTI	LEFTI	RIGHT I	FAR RIGHT
LOST STRAIGHT	11	5000	T. LOST	CENTER	LEFT I	LEFTI	RIGHT I	RIGHTI
TOTALLY LOST	00	500	T. LOST	T.108T	۳. م	۲۰ مما	T. L08T	T. LOST