Premier Energies	Premier Energies	Page : 01 of 01
		Doc. No. : F-IMSP-08/05A
	On Job Training	Rev No. : 00
		Date : 01.06.2024

Training Subjects EL false positives

Trainer Sagar

Location Quality

Date of Training 31.01.2026

Duration30 min

Sr.No.	Participants	Deptt./Area	Designation	Signature
1	N. Mahesh	Module line	Tech.	Mahesh
2	P. Teneela.	Module line.	B.Tech	P. Teneela.
3	K. Seetha mahalakshmi	"	DET	K. Seetha Mahalakshmi
4	Babu Behera	"	DET	Babu Behera
5	P. Mounika	"	Semi skilled	P. Mounika
6	B. Khashikanth	Module line	B.Tech	B. Khashikanth
7				
8				
9				
10				
11				
12				
13				
14				
15				

Train operators and quality inspectors on recognizing equipment-induced false positives vs. genuine defects And Mandate escalation to Engineering and Quality if EL false positives exceed a defined threshold (e.g., >2%).include these in escalation:

Edge lighting non-uniformity
Busbar reflection interference
String tension misalignment at ends
Camera field distortion
Edge electrode overexposure
Image processing threshold miscalibration
Software masking misalignment
If the false alaram is >2 % then
Validation of cell
Escalation email to production/ mnt

Visual Inspection
Check for:
Microcracks
Edge cracks
Cell corner damage
Solder joint cracks
Busbar interruption
Black line / snail trail indication
Finger interruption

Acceptance Criteria

Condition	Decision
Crack visible in EL & confirmed in re-test	REJECT
Crack visible only in machine but not in manual EL	Accept (Record as False Positive)
Visible physical damage	REJECT
No defect confirmed	Accept

Signature Of Trainer

Premier Energies	Premier Energies	Page : 01 of 01
		Doc. No. : F-IMSP-08/05A
	On Job Training	Rev No. : 00
		Date : 01.06.2024

Training Subjects EL false positives

Trainer Sagar

Date of Training 31.01.2026

Location Quality

Duration30 min

Sr.No.	Participants	Deptt./Area	Designation	Signature
1	K. Mrudhula	Production / Module line	E.L operator	K. Mrudhula
2	A. Anusha	production / module line	E.L operator	A. Anusha
3	M. Ramadevi	production / module line	EL operator	M. Ramadevi
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				

Train operators and quality inspectors on recognizing equipment-induced false positives vs. genuine defects And Mandate escalation to Engineering and Quality if EL false positives exceed a defined threshold (e.g., >2%).include these in escalation:

Edge lighting non-uniformity
Busbar reflection interference
String tension misalignment at ends
Camera field distortion
Edge electrode overexposure
Image processing threshold miscalibration
Software masking misalignment
If the false alaram is >2 % then
Validation of cell
Escalation email to production/ mnt

Visual Inspection
Check for:
Microcracks
Edge cracks
Cell corner damage
Solder joint cracks
Busbar interruption
Black line / snail trail indication
Finger interruption

Acceptance Criteria

Condition	Decision
Crack visible in EL & confirmed in re-test	REJECT
Crack visible only in machine but not in manual EL	Accept (Record as False Positive)
Visible physical damage	REJECT
No defect confirmed	Accept

Signature Of Trainer