Marine Surveyor and Logistics
Draft Surveys - Cargo Inspection - Bunquer Surveys
On/Off Hire Surveys - Petroleum Q&Q
Container & Cargo Damage

DRY CERT 2249-1710-2026

Nº	HLBU9375471	INSP. PLACE	Relleno Sanitario Mides	VSL	X-Press Mekong
B / L		CONT. PERSON	Alejandro Neira	CONTAC D/TIME	21-09-2026 14:38
SEALS	HLK 3611040 / DGA-SV3047190 / 156930 / X006378	Init INSP. D/TIME	16-10-2026 08:00 TO 16-10-2026 08:00	Final INSP. D/TIME	17-10-2026 01:00 TO 17-10-2026 01:00
APPOINT.	FIGAL INNOVA SL	ON BEHALF OF	FIGAL INNOVA SL		
SHIPPERS	Calvo Conservas El Salvador S.A. de C.V.	CONSIG/NOTIFY	Nardebalco S.A.		

CONTAINER DESCRIPTION					CAUSE OF INSPECTION					
	20 FOOT	✔ DRY	ISO TANK	FCL	SEALS	BL	CUSTOMS	LEAKING		STUFF / D
✔	40 FOOT	REEFER	FLAT RACK	LCL	CHANGE SEALS		TRANSFER ✔	DAMAGE		CONDITION

Detail of Cause (If necessary)

According to the preliminary account, reefer container HLBU9375471 reportedly sustained contact damage whilst moving astern. The described sequence suggests that an external obstruction scraped along the left-hand side wall, as viewed from the container doors, producing extensive abrasion, followed by a localised perforation and further scraping beyond the affected area.

The nature of the reported damage appears consistent with external mechanical contact. However, the precise circumstances, location and timing of the occurrence, together with the identity of the object involved, remain unconfirmed in the available particulars.

The preliminary account attributes the apparent retention of cooling to the container's insulated construction, comprising an outer skin, an intermediate insulation layer and an inner lining. Nevertheless, the condition of the inner lining and the extent of any disturbance to the insulation were not expressly documented. Accordingly, the available information does not establish whether the structural damage affected the unit's thermal performance or contributed to the apparent thawing of the cargo.

2

Goods	Type of Package			Qty Of Packages		
FROZEN CALVO TUNA	Carton	Drums	Bdls	1st	NA	NA
	Bags ✔	Pallets	Crates	2nd	NA	NA
	Boxes	Bulk	Other	3rd	NA	NA

Package & Marking Description

FROZEN CALVO TUNA

Goods Condition (According Inspector Observations)

PARTIAL THAWING CONTAINER DAMAGE

Details of damage / Shortage (if any) or inspection cause.

Before discharge, the container reportedly exhibited extensive contact damage along its left-hand side wall when viewed from the doors. The damage was described as a prolonged scrape incorporating a perforation of approximately 35 cm in length × 22 cm in width, with scraping continuing beyond the opening.

The available description appears to concern the external wall. No detailed findings were recorded regarding penetration of the inner lining, exposure or displacement of insulation, or damage to the refrigeration machinery. The full structural extent of the damage therefore remains unascertained.
As regards the cargo, the reported abnormalities comprised apparent thawing, softening, loss of firmness, discolouration and frost accumulation. The presence of firmly frozen fish at the bottom suggests that the condition was not uniform throughout the consignment. However, the preliminary report does not quantify the respective proportions of thawed, softened or frozen cargo.

No verified discharged weight, recovery tally or reconciliation against the declared 24,067 kg was supplied. Consequently, neither a physical shortage nor the weight or percentage of cargo affected can presently be established. The apparent deterioration in condition should therefore be distinguished from any unverified shortage in quantity.

Remarks

The inspection and discharge were reportedly carried out at the MIDES landfill facility. The authorities reportedly arrived at the inspection location at 08:00 hrs on 16 October 2026. Following seal cutting at 10:50 hrs, the doors were opened at 10:55 hrs, and discharge commenced at 11:00 hrs. The operation reportedly continued until 01:00 hrs on 17 October 2026, representing approximately fourteen hours from commencement to completion.

The refrigeration plant reportedly remained in operation until 15:35 hrs on 16 October 2026. The account associates its continued operation with the presence of firmly frozen cargo at the bottom, which was difficult to release during discharge. No subsequent refrigeration status or cargo temperature measurements were recorded in the particulars provided.

Although the report records supervision of the discharge through completion, it does not expressly state that every part of the consignment was individually examined. The examination is therefore best described as a visual inspection during discharge, with the quantity actually examined unspecified.
The location of the operation was identified as a landfill facility; however, the preliminary account does not expressly confirm the final disposal method, the quantity disposed of or the issuance of a destruction certificate.

Conclution

On the basis of the preliminary inspection account, reefer container HLBU9375471 appears to have sustained external mechanical contact damage, comprising extensive scraping and a localised side-wall perforation of approximately 35 cm × 22 cm.

The cargo reportedly presented apparent partial thawing, reduced firmness and discolouration, whilst some fish at the bottom remained firmly frozen. These findings suggest an uneven thermal condition within the stow at the time of discharge. The absence of an offensive odour and the reported monitor indication of −20.0°C would not, in isolation, establish satisfactory cargo condition throughout carriage.

The available evidence does not establish a direct causal relationship between the container damage and the apparent cargo deterioration. The onset, duration and extent of any temperature excursion remain undetermined, as do the quantity affected, any physical shortage and the final quantum of loss.
Any further opinion would remain subject to examination of the refrigeration and temperature records, relevant handling and incident reports, the condition of the inner lining and insulation, verified outturn weights, and any cargo assessment or disposal documentation.

Link Picture

COLLECTED DOCUMENTS		QUALITY		INSPECTED CONTAINER		TRANSFER TO CONTAINER	
B/L		✔	PACKING EXAMINATION	Manuf. Nº	NA	Number	NA
PACKING LIST			UN / STUFFED WITNESS	CSC Saf.Apr.	NA	Manuf. Nº	NA
SHIPPING INVOICE		✔	VISUAL EXAMINATION	Max.gross weight	NA Kgs	CSC Saf.Apr.	NA
CARGO MANIFEST		✔	PRODUCT EXAMINATION	Tare	NA Kgs	Seal Nº	NA
COMMERCIAL INVOICE			QUALITY DOCUMENTS	**GENERAL DETAILS**		Max.gross weight	NA Kgs
DELIVERY /RECEIVED RECORD			SANITARY CERTIFICATE		NEW COMMODITY	Tare	NA Kgs
NOTICE OF LOSS / DAMAGE			PHYTOSANITARY CERT.	✔	USED COMMODITY	**SCOPE OF INSPECTION**	
INSURANCE POLICY			FACTORY CERTIFICATE		NET W. NA Kgs	100%	
OTHER			CERTIFICATE OF ORIGIN		GROSS W. NA Kgs	✔ RANDOM	
					VOLUME NA m3	Nº ITEMS	24.067

Name and designation of all persons present at the Survey

German Vega	**Relleno Sanitario MIDES.**
Salvador Peña	**Surveyor, Seguro de Daños.**
Erick Garay	**Surveyor MSL**

PABEL PEÑA

SURVEYOR NAME





MSL SURVEYOR SIGNATURE