



Overview				Site
Inspect No:	1033	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	21/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Vehicle wash	Vehicle Wash HGV		300244

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Findings	
Defects requiring immediate attention	None
Defects requiring attention within a time period	None
Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1044	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	20/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass


Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset #1	Generator Diesel	I21D007036	2001307

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	Genset: Stamford HVSI804W2, S/n: C21B073097. Prime mover: Cummins QSK60-G23, engine no. 33226149



## General Comments

None

<b>Engineer</b>  Graham Willars	
---------------------------------------	---

Industrial Safety Inspections Ltd      Tel: +44 (0) 1675 481779  
 22-23 Amber Business Village  
 Amington  
 Tamworth  
 Staffordshire  
 B77 4RP

Email: info@isisafety.com  
 Web: www.isisafety.com



Overview				Site
Inspect No:	1045	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	20/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 2	Generator Diesel	I21D007047	2001308

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21G306259. Prime mover: Cummins QSK60-G23, engine no. 33226186



## General Comments

Fuel shut offs, emergency stop, remote fire suppression systems, guarding, signage, earthing and insulation all verified.

## Engineer

Graham Willars



Overview				Site
Inspect No:	1078	Page:	1/2	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	21/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 4	Generator Diesel	I21D007025	2001336

Asset Photograph	
Capture photograph of Asset, including asset number	See Photos 1 & 2
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21B073096. Prime mover: QSK60-G23 engine no: 33226137



General Comments	General
None	None

**Engineer**

Graham Willars

## Comments

---



Overview				Site
Inspect No:	1079	Page:	1/2	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	21/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Standby Genset 3	Generator Diesel	I21D007046	2001337


Asset Photograph	
Capture photograph of Asset, including asset number	See Photos 1 & 2
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	Genset: Stamford HVSI804W2 s/n: C21G306260. Prime kover: Cummins QSK60-G23 engine no: 33226185



General Comments	General
None	None

Engineer

Graham Willars



## Comments

---



Overview				Site
Inspect No:	1091	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU01	Handler Air (AHU)	221017-01	2001349

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars





Overview				Site
Inspect No:	1108	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU02	Handler Air (AHU)	221017-02	2001348

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1109	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 5	Handler Air (AHU)	221017-5	2001362

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars





Overview				Site
Inspect No:	1110	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 6	Handler Air (AHU)	221017-06	2001363

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1111	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 8	Handler Air (AHU)	221017-08	2001365

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1112	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 7	Handler Air (AHU)	221017-07	2001364

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1114	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 9	Handler Air (AHU)	221017-09	2001366

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1115	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 3	Handler Air (AHU)	221017-3	2001360

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1117	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Office AHU	Handler Air (AHU)	ACON-02746207	2001347

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1124	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Exit Lane 3	Barrier Traffic	D224207726	2001371

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1127	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 2	Barrier Traffic	D224207719	2001374

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1128	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 3	Barrier Traffic	D224207718	2001375

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1129	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 4	Barrier Traffic	D224207720	2001376

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1130	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 5	Barrier Traffic	D224207715	2001377

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1131	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 6	Barrier Traffic	D224207723	2001378

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1135	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Rail Dock	Gate Powered		2001384

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1137	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU Gantry Access	Ladders & Scaffolding All		2001386

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1138	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Vehicle Building	Ladders & Scaffolding All		2001387

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1139	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Fail

Client-ID	Make / Model	Serial No	ISI Equipment No
Roof Access Ladder	Ladders & Scaffolding All	Roof Access Ladder	2001388

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	Missing horizontal rungs at first rest platform. Installation is not compliant with BS4211
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars





Overview				Site
Inspect No:	1141	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Academy Entrance	Doors Powered Horizontal		2001379

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1142	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Academy Exit	Doors Powered Horizontal		2001380

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars





Overview				Site
Inspect No:	1143	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
AHU 4	Handler Air (AHU)	221017-4	2001361

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1144	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Office AHU 2	Handler Air (AHU)	ACON-02902272	2001367

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1145	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Exit Lane 2	Barrier Traffic	D224507755	2001370

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars



Overview				Site
Inspect No:	1152	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

**Pass**

Client-ID	Make / Model	Serial No	ISI Equipment No
Pedestrian Access	Turnstile Pedestrian		2001383

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

**Engineer**

Graham Willars



Overview				Site
Inspect No:	1153	Page:	1/1	AECOM - MIDLANDS HUB
Job No:	10012			
Customer:	AECOM			
Contact:	Rob Bewick	Date	22/03/2023	Drift Drive Crick Northamptonshire NN6 7GZ
Tel:	7553 226429			

## Pass

Client-ID	Make / Model	Serial No	ISI Equipment No
Entrance Lane 1	Barrier Traffic	D224507753	2001373

Asset Photograph	
Capture photograph of Asset, including asset number	See Photo 1
Hazard Priority and Findings	
Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments
None

Engineer

Graham Willars

