

VEHICLE INSPECTION REPORT

Case: FIR/2024/DL/PSRKP/0452

Date: 13-08-2026

VEHICLE INSPECTION REPORT

Report Id: VIR/PSRKP/0452/2024

Date Of Inspection: 2024-10-16

Time: 10:00 to 13:30

Place: Police Station Rajinder Nagar, Vehicle Examination Yard

INSPECTED BY

Name: ASI Rajender Prasad

Designation: Motor Transport Section, PS Rajinder Nagar

Experience: 18 years in vehicle examination

Assisted By: Constable Mohan Singh, Mechanic

WITNESSES

Item 1:

Name: Mohammed Asif

Designation: Traffic Police Constable

Item 2:

Name: Amit Verma (Accused)

Role: Owner of Vehicle 1, present during inspection

VEHICLE 1

Evidence Id: EVD-0452-001

Type: Motorcycle

Make: Bajaj Auto Ltd.

Model: Pulsar 220F

Variant: Fuel Injected, Disc Brake

Year Of Manufacture: 2020

Registration: DL2SBP1234

Color: Red

Chassis Number: MD2A18FX5LCK12345

Engine Number: DHYCJ51678

Odometer Reading: 48,234 km

Owner: Amit Verma (Accused)

Insurance: ICICI Lombard, Policy 3002/MV/2024/456789, Valid till 14-03-2025

Fitness Certificate: Valid till 13-09-2025

Pollution Certificate: PUC valid till 31-12-2024

EXTERNAL EXAMINATION

Front Fairing: Broken, multiple cracks, partially detached from frame

Headlight Assembly: Completely smashed, glass fragments missing, bulb filament broken (hot shock deformation)

Front Mudguard: Cracked

Front Forks: Right fork bent backward approximately 5 degrees

Front Wheel Rim: Bent at 3 o'clock position, 3mm lateral runout

Front Tyre: MRF Zapper 90/90-17, burst on right side, 2 inch tear

Right Handlebar: Bent downwards approximately 25 degrees

Right Side Body: Scratched, paint transfer from white vehicle

Engine Crankcase: Oil leak from right side gasket (impact stress)

Rear View Mirrors: Right mirror broken, left mirror intact

Brake Levers: Front brake lever in pulled position, suggesting brake application at impact

Leg Guard: Right leg guard bent inwards

Silencer: Scratched, minor dent

Sarai Guard: Intact

Number Plates: Front plate broken, rear plate intact, HSRP type

MECHANICAL EXAMINATION

Engine: Starts with difficulty, abnormal noise from crankcase area

Compression: Normal (8.5:1 compression test OK)

Clutch: Functional, free play 2mm (spec 2-3mm)

Gearbox: All 5 gears engaging, no jumping

Front Brake: Disc brake functional, pad thickness 3mm (spec new 4mm, min 1mm)

Rear Brake: Drum brake functional, pedal free play 20mm (spec 20-30mm)

Brake Fluid: Level adequate, DOT 4

Chain Sprocket: Chain slack 35mm (spec 25-35mm), sprocket wear normal

Steering: Handlebar movement restricted on right side due to bend

Suspension Front: Right fork tube bent, seal leaking oil

Suspension Rear: Nitrox shock absorbers normal, no leak

Electrical: Headlight non-functional (smashed), indicators right front broken, rest functional

Horn: Functional

Speedometer: Needle stuck at 55 kmph mark, console cracked

Fuel Tank: No leak, cap intact

BRAKE TEST

Front Brake Efficiency: Adequate at time of accident (pad thickness confirms regular maintenance)

Rear Brake Efficiency: Adequate

Brake Application Evidence: Front brake lever found in applied position post-accident, consistent with emergency braking attempt

TYRE CONDITION

Front Tyre: Burst due to impact, pre-accident tread depth 3.2mm (adequate), no irregular wear

Rear Tyre: Tread depth 4.5mm (good), even wear, no cuts or bulges

Tyre Pressure Estimated: Front 28 psi, Rear 32 psi (normal range from deformation pattern)

VISIBILITY AIDS

Headlight: Smashed, filament analysis shows ON at impact (hot shock)

Tail Light: Functional

Indicators: Left functional, right front broken, right rear functional

Reflectors: Front broken, rear present

SAFETY FEATURES

Sarai Guard: Present, ISI marked

Leg Guard: Present, bent but absorbed impact

Rear View Mirrors: One broken, one present

Damage Summary: Moderate to severe frontal and right side damage consistent with collision at 50-60 kmph with another vehicle laterally. All damage is accident-related. Vehicle was in roadworthy condition before accident with all systems functional.

VEHICLE 2

Evidence Id: EVD-0452-002

Type: Scooter

Make: Honda Motorcycle & Scooter India
Model: Activa 6G
Variant: DLX
Year Of Manufacture: 2022
Registration: DL5SCT5678
Color: Pearl White
Chassis Number: ME4JF614AMT67890
Engine Number: JF61E3456789
Odometer Reading: 12,456 km
Owner: Rajesh Kumar Sharma (Victim)
Insurance: New India Assurance, Policy NIA/MV/2024/890123, Valid till 22-06-2025
Fitness Certificate: Not required (less than 15 years)
Pollution Certificate: PUC valid till 30-09-2025

EXTERNAL EXAMINATION

Right Body Panel: Deep scrape marks, paint scratched off in 35cm x 20cm area, dented inward 2.5cm
Right Side Trim: Broken, pieces found at accident site
Right Rear View Mirror: Bracket broken, mirror glass cracked
Front Apron: Scratched, minor crack
Headlight: Scratched but intact, functional
Right Indicator: Lens broken, bulb exposed but functional
Floor Panel: Scratched on right edge
Grab Rail: Slightly bent on right side
Number Plate Rear: Intact
Seat: Cover torn on right side
Exhaust Muffler: Scratched, minor dent
Center Stand: Slightly bent

MECHANICAL EXAMINATION

Engine: Starts in one crank, runs smooth, no abnormal noise
Transmission: CVT, smooth operation, belt condition good
Front Brake: Drum brake functional, brake shoe lining 3mm
Rear Brake: Drum brake functional, brake shoe lining 2.5mm
Brake Lever Right: Bent downward 15 degrees from impact, brake still functional
Steering: Handlebar alignment slightly off (5 degrees to left), steering movement smooth
Suspension Front: Bottom link functional, no leak
Suspension Rear: Spring loaded hydraulic, functional, no leak

Electrical: All lights functional except right front indicator lens broken

Horn: Functional

Speedometer: Functional, analog type

Fuel Gauge: Functional, showing 1/4 tank

Fuel Tank: Metal tank under seat, no leak

Battery: 12V 5Ah, functional

BRAKE TEST

Front Brake Efficiency: Adequate

Rear Brake Efficiency: Adequate

Combined Braking System: Functional (Combi-Brake System standard on Activa 6G)

TYRE CONDITION

Front Tyre: MRF 90/100-10, tread depth 4.0mm (good), even wear, no damage

Rear Tyre: MRF 90/100-10, tread depth 3.5mm (adequate), even wear, no damage

Tyre Pressure Estimated: Front 22 psi, Rear 29 psi (normal)

VISIBILITY AIDS

Headlight: Functional, always-on type (AC-DC), ON at time of accident

Tail Light: Functional

Indicators: Right front lens broken (bulb working), others functional

Reflectors: All present

SAFETY FEATURES

Combi Brake: Functional

Side Stand Indicator: Functional (engine cuts off if stand down)

Rear View Mirrors: Right broken, left intact

Damage Summary: Moderate right side body damage consistent with lateral impact from another vehicle. Structural integrity of frame intact. Scooter was in excellent condition before accident. All systems functional. Damage is 100% accident-related.

COMPARATIVE ANALYSIS

Impact Correlation: Damage on Pulsar (front-right) matches damage on Activa (right-center) in height, angle, and force pattern. Paint transfer confirmed on both vehicles in FSL report.

Pre Accident Condition: Both vehicles were roadworthy and properly maintained. No pre-existing mechanical defects contributed to the accident.

Post Accident Assessment: Both vehicles are repairable. Estimated repair cost: Pulsar - ■12,000-15,000, Activa - ■8,000-10,000.

Inspector Opinion: Based on vehicle examination, the accident dynamics are clear. The Pulsar struck the Activa at a near-perpendicular angle with the front of the Pulsar impacting the right side of the Activa. The damage depth and deformation on the Activa (2.5cm dent, 35cm scrape) indicates a significant lateral impact force, confirming the FSL-calculated impact speed of 50-58 kmph for the Pulsar. The stuck speedometer needle at 55 kmph corroborates this. No mechanical failure contributed to the accident. Both vehicles' braking systems were functional and the Pulsar rider did attempt emergency braking (front brake lever in applied position, 4.2m skid mark) but at the speed he was traveling, collision was unavoidable from the point braking was initiated.

Signature: ASI Rajender Prasad, Motor Transport Section

Date: 2024-10-16