CSE416 "Digital Control" Final Exam Model Answer January, 2021

Question (1):

1. a.

$$C = [B_c A_c B_c] = \begin{bmatrix} 0 & 1 \\ 1 & 0 \end{bmatrix}$$

Controllability matrix has full rank, and the system is controllable.

$$\mathcal{O} = \begin{bmatrix} C \\ CA_C \end{bmatrix} = \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix}$$

Observability matrix has full rank, and the system is observable.

1. b.

$$\Phi(s) = (sI - A)^{-1} = \begin{bmatrix} s & -1 \\ 1 & s \end{bmatrix}^{-1} = \begin{bmatrix} \frac{s}{s^2 + 1} & \frac{1}{s^2 + 1} \\ \frac{-1}{s^2 + 1} & \frac{s}{s^2 + 1} \end{bmatrix}$$

$$A = \phi(T) = \begin{bmatrix} \cos T & \sin T \\ -\sin T & \cos T \end{bmatrix}$$

$$B = \int_0^T \phi(\tau) B_c d\tau = \int_0^T \begin{bmatrix} \cos \tau & \sin \tau \\ -\sin \tau & \cos \tau \end{bmatrix} \begin{bmatrix} 0 \\ 1 \end{bmatrix} d\tau = \int_0^T \begin{bmatrix} \sin \tau \\ \cos \tau \end{bmatrix} d\tau = \begin{bmatrix} -\cos \tau \\ \sin \tau \end{bmatrix}_0^T$$

$$B = \begin{bmatrix} 1 - \cos T \\ \sin T \end{bmatrix}$$

Then, the discrete state variable model is:

$$\begin{bmatrix} x_1(k+1) \\ x_2(k+1) \end{bmatrix} = \begin{bmatrix} \cos T & \sin T \\ -\sin T & \cos T \end{bmatrix} \begin{bmatrix} x_1(k) \\ x_2(k) \end{bmatrix} + \begin{bmatrix} 1 - \cos T \\ \sin T \end{bmatrix} u(k)$$

1. c.

$$\mathcal{C} = [B \ AB] = \begin{bmatrix} 1 - \cos T & \cos T - \cos^2 T + \sin^2 T \\ \sin T & -\sin T + 2\sin T\cos T \end{bmatrix}$$

$$\Delta(\mathcal{C}) = -\sin T + 2\sin T\cos T + \cos T\sin T - 2\sin T\cos^2 T - \sin T\cos T + \sin T\cos^2 T$$

$$-\sin^3 T$$

$$\Delta(\mathcal{C}) = 2\sin T\cos T - \sin T\cos^2 T - \sin T(1 + \sin^2 T)$$

$$\Delta(\mathcal{C}) = 2\sin T\cos T - \sin T\cos^2 T - 2\sin T + \sin T\cos^2 T$$

$$\Delta(\mathcal{C}) = -2\sin T(1 - \cos T)$$

The system loses controllability for $T = n\pi$. n = 0,1,2,...

$$\mathcal{O} = \begin{bmatrix} C \\ CA \end{bmatrix} = \begin{bmatrix} 1 & 0 \\ \cos T & \sin T \end{bmatrix}$$
$$\Delta(\mathcal{O}) = \sin T$$

The system loses observability for $T = n\pi$. n = 0,1,2,...

1. d.

Transfer function for analog system:

$$G(s) = C(sI - A_c)^{-1}B_c + D$$

$$G(s) = \begin{bmatrix} 1 & 0 \end{bmatrix} \begin{bmatrix} s & -1 \\ 1 & s \end{bmatrix}^{-1} \begin{bmatrix} 0 \\ 1 \end{bmatrix}$$

$$G(s) = \begin{bmatrix} 1 & 0 \end{bmatrix} \begin{bmatrix} \frac{s}{s^2 + 1} & \frac{1}{s^2 + 1} \\ -1 & \frac{s}{s^2 + 1} \end{bmatrix} \begin{bmatrix} 0 \\ 1 \end{bmatrix} = \frac{1}{s^2 + 1}$$

Transfer function for digital system:

$$G(z) = C(zI - A)^{-1}B + D$$

$$G(z) = \begin{bmatrix} 1 & 0 \end{bmatrix} \begin{bmatrix} z - \cos T & -\sin T \\ \sin T & z - \cos T \end{bmatrix}^{-1} \begin{bmatrix} 1 - \cos T \\ \sin T \end{bmatrix}$$

$$G(z) = \frac{1}{(z - \cos T)^2 \sin^2 T} \begin{bmatrix} 1 & 0 \end{bmatrix} \begin{bmatrix} z - \cos T & \sin T \\ -\sin T & z - \cos T \end{bmatrix} \begin{bmatrix} 1 - \cos T \\ \sin T \end{bmatrix}$$


$$G(z) = \frac{(z - \cos T)(1 - \cos T) + \sin^2 T}{(z - \cos T)^2 \sin^2 T}$$

2.

$$Q(z) = z^2 + \alpha_1 z + \alpha_2.$$

1
$$Q(1) = 1 + \alpha_1 + \alpha_2 > 0$$

2 $(-1)^2 Q(-1) = 1 - \alpha_1 + \alpha_2 > 0$
3 $|\alpha_2| < 1 \rightarrow -1 < \alpha_2 < 1$



Question (2):

1. a.

$$M(z) = E(z) - 0.9z^{-1}E(z) + z^{-1}M(z)$$
$$(1 - z^{-1})M(z) = (1 - 0.9z^{-1})E(z)$$

$$D(z) = \frac{M(z)}{E(z)} = \frac{z - 0.9}{z - 1}$$

1. b.

$$G(z) = Z\left\{\frac{1 - e^{-Ts}}{s} \frac{1}{s+2}\right\} = (1 - z^{-1})Z\left\{\frac{1}{s(s+2)}\right\} = (1 - z^{-1})Z\left\{\frac{0.5}{s} - \frac{0.5}{s+2}\right\}$$

$$G(z) = \frac{z - 1}{z} \left(\frac{0.5z}{z - 1} - \frac{0.5z}{z - e^{-2}}\right)$$

$$G(z) = \frac{z - 1}{z} \left(\frac{0.5z(z - e^{-2}) - 0.5z(z - 1)}{(z - 1)(z - e^{-2})}\right)$$

$$G(z) = \frac{0.4323}{z - 0.1353}$$

The open loop transfer function D(z)G(z) has one pole at z-1

The system is type one, therefore for a unit-step input the steady state error is zero and the steady state response is 1.

1. c.

The closed loop TF is
$$T(z) = \frac{D(z)G(z)}{1+D(z)G(z)} = \frac{0.4323z-0.3891}{z^2-0.703z-0.2538}$$

Closed loop poles are 0.9658, -0.2628

The more dominant pole is 0.9658.

Time constant
$$\tau = -\frac{T}{\ln r} = -\frac{1}{\ln(0.9658)} = 28.74 \ seconds$$

1. d.

Approximate settling time = $4\tau = 114.95$ *seconds*

Also 5τ is correct.

1. e.

Unit step response

$$C(z) = \frac{0.4323z(z - 0.9)}{(z - 0.9658)(z + 0.2628)(z - 1)}$$

$$\frac{C(z)}{z} = \frac{1}{z - 1} - \frac{0.6760}{z - 0.9658} - \frac{0.3240}{z + 0.2628}$$


$$C(z) = \frac{z}{z - 1} - \frac{0.6760z}{z - 0.9658} - \frac{0.3240z}{z + 0.2628}$$

$$c(k) = 1 - 0.6760(0.9658)^k - 0.3240(-0.2628)^k$$

1. f.

Substituting with $k = 115 \rightarrow c(115) = 0.988$

2.



Question (3):


1.

$$G(z) = \frac{1.037}{z - 0.7408}$$

We first apply the bilinear transform:

$$z = \frac{1 + (\frac{T}{2})w}{1 - (\frac{T}{2})w} = \frac{1 + 0.3w}{1 - 0.3w}$$
$$G(w) = -0.5957 \frac{w - 3.3333}{w}$$

$$G(j\omega) = 4\frac{1 - \frac{j\omega}{3.3333}}{1 + \frac{j\omega}{0.4963}}$$



2.

$$e_{SS} = \frac{1}{1 + \lim_{z \to 1} G(z)H(z)} = \frac{1}{1 + \lim_{z \to 1} \frac{0.04148}{z - 0.7408}} = \frac{1}{1 + 0.16} = 0.862$$

The steady state error is 0.862 or 86.2%

3.

To achieve a steady state error of 0.05, we will design a phase lag with a dc gain K such that:

$$0.05 = \frac{1}{1 + 0.16K} \to 0.05 + 0.05 \times 0.16K = 1 \to K = 118.75$$

The required phase margin is $\phi_m = 45^{\circ}$

Choose the phase crossover frequency as:

$$\angle G(j\omega_{w1}) = -180^{\circ} + \phi_m + 5^{\circ} = -130^{\circ}$$

From your sketched bode diagram, $\omega_{w1} \approx 4$

The zero location
$$\omega_{w0} = 0.1\omega_{w1} = 0.4$$

The pole location $\omega_{wp} = \frac{0.1\omega_{w1}}{a_0|G(j\omega_{w1})|\times H} = \frac{0.4}{118.75\times0.7694\times0.04} = 0.1094$

The compensator in the w-plane $D(w) = 118.75 \frac{1 + \frac{W}{0.4}}{1 + \frac{W}{0.1094}}$ Back to z-plane using bilinear transform (inverse) $w = \frac{2}{T} \frac{z-1}{z+1}$

$$D(z) = \frac{35.22z - 27.67}{z - 0.9364}$$

4.

$$\frac{M(z)}{E(z)} = \frac{35.22z - 27.67}{z - 0.9364} \rightarrow zM(z) - 0.9364M(z) = 35.22zE(z) - 27.67E(z)$$

$$m(k+1) - 0.9364m(k) = 35.22e(k+1) - 27.67e(k)$$

$$m(k) = 35.22e(k) - 27.67e(k-1) + 0.9364m(k-1)$$

Question (4):

1.

$$\tau = 4, \zeta = 0.707$$

$$\ln r = -\frac{T}{\tau} = -\frac{1}{4} \to r = 0.7788$$

$$\theta^2 = (\ln r)^2 \left(\frac{1}{\zeta^2} - 1\right) = \frac{1}{16} \times \left(\frac{1}{0.707^2} - 1\right) \to \theta = \pm 0.25$$

The required poles are $z_{1.2} = 0.7788 \angle \pm 0.25$

$$\alpha_c(z) = z^2 - 2r\cos\theta \ z + r^2$$

$$\alpha_c(z) = z^2 - 2 \times 0.7788 \cos 0.25 \ z + (0.7788)^2$$

Desired characteristic equation is: $\alpha_c(z) = z^2 - 1.5092z + 0.6065$

$$\alpha_c(A) = \begin{bmatrix} 1 & 1 \\ 0 & 1 \end{bmatrix}^2 - 1.5092 \begin{bmatrix} 1 & 1 \\ 0 & 1 \end{bmatrix} + 0.6065 = \begin{bmatrix} 0.0973 & 0.4908 \\ 0 & 0.0973 \end{bmatrix}$$

Applying Ackermann's formula:

$$K = \begin{bmatrix} 0 & 1 \end{bmatrix} \begin{bmatrix} B & AB \end{bmatrix}^{-1} \alpha_c(A) = \begin{bmatrix} 0.3892 & 1.7686 \end{bmatrix}$$

2.

$$A_{aa} = 1$$
, $A_{ab} = 1$, $A_{ba} = 0$, $A_{bb} = 1$, $B_a = 0.125$, $B_b = 0.25$
The observer dynamics:

 $\tau = 2$

$$\alpha_e(z) = z - e^{-\frac{T}{\tau}} = z - 0.6065$$
 $\alpha_e(A_{bb}) = A_{bb} - 0.6065 = 1 - 0.6065 = 0.3935$
 $G = \alpha_e(A_{bb})[A_{ab}]^{-1}[1] = 0.3935$

$$\mathbf{q}_b(k+1) = (\mathbf{A}_{bb} - \mathbf{G}\mathbf{A}_{ab})\mathbf{q}_b(k) + \mathbf{G}\mathbf{y}(k+1) + (\mathbf{A}_{ba} - \mathbf{G}\mathbf{A}_{aa})\mathbf{y}(k) + (\mathbf{B}_b - \mathbf{G}\mathbf{B}_a)\mathbf{u}(k)$$

$$\mathbf{q}_b(k) = 0.6065\mathbf{q}_b(k-1) + 0.3935\mathbf{y}(k) - 0.3935\mathbf{y}(k-1) + 0.2008\mathbf{u}(k)$$

3.

$$D_{ce}(z) = \frac{-U(z)}{Y(z)} = K_1 + \mathbf{K}_b[z\mathbf{I} - \mathbf{A}_{bb} + \mathbf{G}\mathbf{A}_{ab} + (\mathbf{B}_b - \mathbf{G}\mathbf{B}_a)\mathbf{K}_b]^{-1}$$
$$\cdot [\mathbf{G}z + \{\mathbf{A}_{ba} - \mathbf{G}\mathbf{A}_{aa} - K_1(\mathbf{B}_b - \mathbf{G}\mathbf{B}_a)\}]$$

```
D_{ce}(z) = 0.3892 + 1.7686(z - 0.2514)^{-1}.(0.3935z - 0.4717) = \frac{1.085z - 0.9321}{z - 0.2514}
4.
       1.085z - 0.9321
M(z)
\frac{\zeta}{E(z)} = \frac{1}{z - 0.2514}
zM(z) - 0.2514M(z) = 1.085zE(z) - 0.9321E(z)
m(k) = 1.085e(k) - 0.9321e(k-1) - 0.2514m(k-1)
Define variables error = 0, control action = 0, previous error = 0,
previous control action = 0;
Start loop:
     read error;
     control_action= .085*error-0.9321*previous_error-
                            0.2514*previous control action;
     previous_error = error;
     previous control action = control action;
     output control action;
end loop.
```