

Chat incident

Priorité : P3

Confiance : MEDIUM

ID incident	INC-CCU-38A8B275
Généré le	2026-08-19T10:52:19.331442+00:00
Détecté le	2026-08-19T10:52:19.331442+00:00
ID client	N/A
ID commande	--
Type de produit	fibres
Catégorie	fibres

Ce qui s'est passé

what does svc-fiber-12345 mean?

Cause racine

Perte de signal fibre optique

Sources

- log-001
- log-002
- acc-12345
- ord-2026-001

Recherche d'incident similaire

Statut:	Nouveau ticket créé
ID ticket:	TICK-CCU-A614385C
Score de similarité:	0.0

Recommandation

What happened: The incident involves service 'svc-fiber-12345' with a CLIENT_ID 500 subscription for customer 'Dupont SARL'. The service is currently in the 'InProgress' state due to ongoing CPE provisioning. At 14:23:11 UTC on [PHONE_REDACTED], an error was logged by the OLT (olt-north-03) indicating a detected optical signal loss on PON interface 7/3/2 with a received optical power of -32 dBm, which is below the threshold of -28 dBm. This was followed by a warning at 14:24:05 UTC, stating that the CPE provisioning attempt was refused because the service was in a DOWN state as reported by the OLT. No similar tickets were found in the historical records, as indicated by the 'Aucun ticket historique similaire trouvé' message. Why: The root cause of the incident is a detected optical signal loss on the PON interface 7/3/2, as evidenced by the logs from the OLT. The received optical power (-32 dBm) is below the threshold (-28 dBm), leading to the service being marked as DOWN. This condition prevented the CPE provisioning attempt, which was in progress. The service is part of the ongoing CPE provisioning process, which is a risk factor. Recommendation: The team should investigate the physical connection of the fiber optic cable on the PON interface 7/3/2 to ensure there are no physical disruptions. Additionally, the OLT configuration and the CPE provisioning process should be reviewed to ensure they are functioning correctly. Regular maintenance and monitoring of the fiber optic infrastructure should be prioritized to prevent such incidents in the future.