

Test fibre

Priorité : P1

Confiance : MEDIUM

ID incident	INC-CCU-A756F2C1
Généré le	2026-08-18T22:59:46.715384+00:00
Détecté le	2026-08-18T22:59:46.715384+00:00
ID client	acc-12345
ID commande	ord-2026-001
Type de produit	fibre
Catégorie	fibre

Ce qui s'est passé

Client acc-12345, service svc-fiber-12345, commande ord-[PHONE_REDACTED]. acc-12345 fibre.

Cause racine

Perte de signal fibre optique

Sources

- log-001
- log-002
- acc-12345
- ord-2026-001

Recherche d'incident similaire

Statut:	Nouveau ticket créé
ID ticket:	TICK-CCU-C8317413
Score de similarité:	0.0

Recommandation

What happened: The incident involves a fiber cut for the customer acc-12345, specifically for the service svc-fiber-12345, as part of the order ord-[PHONE_REDACTED]. The fiber service was interrupted, leading to a loss of internet connectivity for the customer. The logs indicate a detected optical signal loss on the OLT interface PON 7/3/2, with a received optical power of -32 dBm, which is below the threshold of -28 dBm. No similar tickets were found in the historical records, suggesting this is a unique event for the customer. The customer is a SME (PME) with the service 'acc-12345 500' active at the address [ADDRESS_REDACTED], 75011 Paris. The order is currently in progress, with the reason being the provisioning of the CPE (acc-12345) for the service. The risk factor is the ongoing CPE provisioning, which could potentially affect the service stability. Why: The root cause of the incident is a detected optical signal loss on the OLT interface PON 7/3/2, as evidenced by the logs from the OLT system. The received optical power (-32 dBm) is below the threshold (-28 dBm), indicating a significant reduction in the signal strength, which is likely the reason for the service disruption. The logs also show a warning message from the CCU provisioner indicating that the provisioning of the CPE was refused due to the service being in a DOWN state on the OLT. This suggests that the provisioning process was halted due to the detected signal loss, leading to the service outage. Recommendation: Given the root cause and the context, the recommendation is to perform a detailed inspection of the fiber connection at the OLT interface PON 7/3/2. The team should verify the physical condition of the fiber and check for any potential issues such as damage or loose connections. Additionally, the team should monitor the status of the CPE provisioning process and ensure that it is completed successfully once the fiber connection is restored. This will help in preventing future disruptions and ensuring the smooth operation of the service.