
omp. A	rch	Unit	- 2				De	TE:	13/04/	202
Yω	con	get (ærfo	mano	ce bu	\ :				
		rallel								
	+	1								
		V								
	PIPE	ELININ	G							
		EVA110		5.,,,,,,		~	0 1-		uho Porv	da
		EXAMP	œ:	YOU	con a	speit th	oi, ei	some	the Cour phases	July.
					14	14	4H			
	n	= 3 = W	,d,c		_ M -	→ D -	→ <u>·</u> ··			
				wash		dryer		close		
					0					
						W -	⇒ D	→ [·	
		Pipelin	ning i	s US	etue !	when yo	od uc	ve s	മാരവ	
						-				
	0,		, >	time	to p	erform				
	A King	~3n		co	EED -	LID.				
	, gr	n+2	-	, 5	CED -	OF				
			best t	·1000						
		34		3						
		V1+2	n→∞							
IHRE	EE	REQUI	REM	ENTS	FOR	PIPELI	NING			
	You	mus	have	2 0	0100	oss tha	t con	he	divided	

- (1) You must have a process that can be divided into phases.
- 2 Each phase has to use different hardware
- (3) Each phase needs to have approx. Some time length.



HOW CAN WE NOT LOSE CLOCK CYCLES WHEN WE HAVE TO JUMP? LOOP UNROLLING -> reduce number of branches.

Done by compiler INTEL PENTIUM → has a lot of pipelining (2GH) components (2GH) > IBM PowerPC G4
(Motorola)
auchitecture Apple had an agreement with IBM to use PowerPC G4's.