
1 heat the billet
(steel ≈ 1200 °C)
2 blows between dies
3 trim the flash