

1 heat the billet
(steel ≈ 1200 °C)

2 blows between dies

3 trim the flash