

# Metro Kitchen Equipment Service

## SERVICE REPORT

Work Order: WO-680643 | Date: 04/04/2025

### Client Information

Client	Hogan PLC
Address	328 Aaron Hills Suite 435, New Thomas, SD 17872
Phone	+1-625-717-8172x798

### Equipment Information

Field	Value
Machine Type	Fryers
Model	DeepFry Pro 450
Serial Number	SN95949209

### Service Details

#### Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

#### Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

### Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

## Technician Information

---

<b>Technician Name</b>	Sarah Williams
<b>Technician ID</b>	TECH-015
<b>Certification</b>	CFESA Certified Master
<b>Arrival Time</b>	08:10
<b>Labor Hours</b>	3.77

---

**Technician Signature:** \_\_\_\_\_ **Date:** \_\_\_\_\_

---

*Metro Kitchen Equipment Service | 24/7 Service | (555) 123-4567*

*www.foodservicetech.com | service@foodservicetech.com*