

National Restaurant Repair

SERVICE REPORT

Work Order: WO-545731 | Date: 12/08/2025

Client Information

| | |
|---------|---|
| Client | Cox-Donovan |
| Address | 87532 Charles Isle, Port Kathleen, VI 16589 |
| Phone | 381-570-9456x314 |

Equipment Information

| Field | Value |
|---------------|-----------------|
| Machine Type | Fryers |
| Model | DeepFry Pro 450 |
| Serial Number | SN22317463 |

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

| | |
|------------------------|----------------------------|
| Technician Name | Lisa Martinez |
| Technician ID | TECH-031 |
| Certification | CFESA Certified Specialist |
| Arrival Time | 19:42 |
| Labor Hours | 2.2 |

Technician Signature: _____ **Date:** _____

National Restaurant Repair | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com