

Metro Kitchen Equipment Service

SERVICE REPORT

Work Order: WO-865608 | Date: 12/26/2024

Client Information

Client	Dunlap and Sons
Address	55232 Andrew Park Apt. 521, Gonzalesstad, NV 60843
Phone	713-793-5498x308

Equipment Information

Field	Value
Machine Type	Fryers
Model	TurboCrisp 2000
Serial Number	SN66773130

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	David Chen
Technician ID	TECH-012
Certification	EPA Type I/II Certified
Arrival Time	17:54
Labor Hours	3.68

Technician Signature: _____ **Date:** _____

Metro Kitchen Equipment Service | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com