

National Restaurant Repair

SERVICE REPORT

Work Order: WO-498035 | Date: 05/07/2024

Client Information

Client	Browning-Sparks
Address	USS Grant, FPO AP 47775
Phone	3829463960

Equipment Information

Field	Value
Machine Type	Fryers
Model	TurboCrisp 2000
Serial Number	SN76627720

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	David Chen
Technician ID	TECH-012
Certification	EPA Type I/II Certified
Arrival Time	18:39
Labor Hours	4.0

Technician Signature: _____ **Date:** _____

National Restaurant Repair | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com