

FoodService Tech Pros

SERVICE REPORT

Work Order: WO-271270 | Date: 09/29/2025

Client Information

Client	Scott, Johnson and Ross
Address	06397 Richard Ville, Robertsberg, ND 89346
Phone	694-342-4790x67688

Equipment Information

Field	Value
Machine Type	Fryers
Model	FryMaster XL-4000
Serial Number	SN10353761

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Mike Johnson
Technician ID	TECH-001
Certification	EPA Universal Certified
Arrival Time	14:30
Labor Hours	3.3

Technician Signature: _____ **Date:** _____

FoodService Tech Pros | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com